

Cleanup Site Details

Cleanup Site ID: 4359
Cleanup Site ID: 4359 **Facility/Site ID:** 458 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Cameron Yakima Inc [Glossary](#)
Alternate Names: Cameron Yakima Inc

LOCATION
Address: 1414 S 1ST ST **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.58456 **Longitude:** -120.49625 **WRIA:** 37 **Legislative District:** 14 **Congressional District:** 4 **TRS:** 13N 19E 30

DETAIL

Status: Construction Complete-Performance Monitoring	NFA Received? No	Is PSI site? No
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Parker, Kyle	Responsible Unit: Central	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Cameron Yakima Inc	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	CE	Parker, Kyle	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS
MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans	C				C	
Halogenated Solvents	C	C	S		S	
Non-Halogenated Solvents	C	C	S		S	

Key:

B - Below Cleanup Level	C - Confirmed Above Cleanup Level	RA - Remediated-Above
S - Suspected	R - Remediated	RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	In Process		
Order/Decree/Amendment	In Process		
Initial Investigation / Federal Preliminary Assessment	Completed		9/6/1985
Remedial Investigation and/or Feasibility Study	Canceled	10/10/1990	4/10/1992
Site Hazard Assessment/Federal Site Inspection	Completed	1/15/1991	6/30/1991
Hazardous Sites Listing/NPL	Completed		8/27/1991

Cleanup Site Details

Cleanup Site ID: 4359

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	Completed	2/11/1992	
Remedial Investigation and/or Feasibility Study	Completed	3/31/1994	9/29/2000
Interim Action	Completed	7/16/1996	10/31/1996
Interim Action	Completed	9/30/1999	9/30/2000
Interim Action - Performance Monitoring	In Process	9/30/2000	