

# Cleanup Site Details

Cleanup Site ID: 4402

Cleanup Site ID: 4402      Facility/Site ID: 2757      UST ID: 783      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Jeld Wen      [Glossary](#)

**Alternate Names:** E A NORD COMPANY, EA NORD COMPANY, Jeld Wen, JELD WEN INC DBA JELD WEN EVER & NOR, JELD WEN OF EVERETT NORD DOOR, NORD DOOR CO

## LOCATION

**Address:** 300 W MARINE VIEW DR      **City:** EVERETT      **Zip Code:** 98201      **County:** Snohomish  
**Latitude:** 48.01555      **Longitude:** -122.21211      **WRIA:** 7      **Legislative District:** 38      **Congressional District:** 2      **TRS:** 29N 5E 7

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** Yes  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 5 - Lowest Assessed Risk      **NFA Reason:** N/A      **Brownfield?** No  
**Site Manager:** Winslow, Frank      **Responsible Unit:** Headquarters      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Jeld Wen	Sediment	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted
Jeld Wen	Upland	Cleanup Started	HQ	Winslow, Frank	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	C	C			C	
Dioxins/Furans	C	C		C		
Other Deleterious Substances				C		
Other Non-Halogenated Organics	C	C				
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				
Petroleum-Other			B			
Phenolic Compounds		C				
Polychlorinated biPhenyls (PCB)		C		C		
Polycyclic Aromatic Hydrocarbons	C	C		C	C	

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 4402

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Order/Decree/Amendment	In Process		
LUST - Report Received	Completed		11/14/1990
LUST - Notification	Completed		12/26/1990
Site Discovery/Release Report Received	Completed		12/26/1990
Site Hazard Assessment/Federal Site Inspection	Completed	4/15/1991	6/30/1991
Hazardous Sites Listing/NPL	Completed		8/30/1991
LUST - Report Received	Completed		11/13/1991
Remedial Investigation and/or Feasibility Study	Completed	10/28/2008	12/30/2021
Initial Investigation / Federal Preliminary Assessment	Completed		5/3/2011
Early Notice Letter(s)	Completed		10/3/2011
Non-LUST Ind Report Received	Completed		2/25/2014
Cleanup Action Plan	Completed	1/1/2022	8/30/2023
Order/Decree/Amendment	In Process	2/13/2023	
Cleanup Action - Engineering Design	In Process	7/1/2023	