

# Cleanup Site Details

Cleanup Site ID: 4484

Cleanup Site ID: 4484      Facility/Site ID: 95275518      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Irondale Iron & Steel Plant      [Glossary](#)

Alternate Names: FORMER IRONDALE IRON & STEEL PLANT, Irondale Iron & Steel Plant, IRONDALE IRON & STEEL PLANT FORMER

## LOCATION

Address: 562 E MOORE ST      City: PORT HADLOCK      Zip Code: 98339      County: Jefferson  
Latitude: 48.04436      Longitude: -122.76907      WRIA: 17      Legislative District: 24      Congressional District: 6      TRS: 30N 1W 35

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? Yes  
Statute: MTCA      NFA Date: 8/22/2016      Current VCP? No      Past VCP? No  
Site Rank: 1 - Highest Assessed Risk      NFA Reason: Ecology Supervised/Conducted Cleanup      Brownfield? No  
Site Manager: Teel, Steve      Responsible Unit: Southwest      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
IRONDALE IRON & STEEL PLANT FORMER	Upland	No Further Action Required	SW	Teel, Steve	Ecology-supervised or conducted
Irondale Sediment	Sediment	No Further Action Required	SW	Teel, Steve	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil	Restrict Land Use, Prohibit Soil Disturbance	7/5/2016	600593	Jefferson	001353001

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Arsenic	RA	B		B		
Lead	RA	B		B		
Metals - Other	RA	RB		B		
Petroleum-Diesel	RB	RB		RB		
Petroleum-Other	RB	RB		RB		
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	RB	RB		RB		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Hazard Assessment	Completed	10/10/2001	12/28/2001
Initial Investigation / Federal Preliminary Assessment	Completed		11/30/2001

# Cleanup Site Details

Cleanup Site ID: 4484

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Status Changed to NFA	Completed		12/28/2001
Remove site from Hazardous Sites List	Completed		12/28/2001
Early Notice Letter(s)	Completed		3/9/2006
Initial Investigation / Federal Preliminary Assessment	Completed		3/9/2006
Remedial Investigation and/or Feasibility Study	Completed	11/1/2006	8/31/2009
Site Hazard Assessment	Completed	11/9/2006	7/27/2007
Remedial Investigation and/or Feasibility Study	Completed	2/14/2007	12/31/2010
Hazardous Sites Listing	Completed		7/27/2007
Reopen Site	Completed		7/27/2007
Cleanup Action Plan	Completed	1/1/2009	1/22/2010
Cleanup Action - Engineering Design	Completed	12/9/2010	5/1/2012
Cleanup - Construction	Completed	6/27/2012	12/31/2012
Cleanup - Performance Monitoring	Completed	9/10/2012	10/23/2012
Monitoring	Completed	1/4/2013	2/26/2014
Remove site from Hazardous Sites List	Completed		8/22/2016
Site Status Changed to NFA	Completed		8/22/2016
Periodic Review	Planned	8/23/2021	1/1/1900