

Cleanup Site Details

Cleanup Site ID: 4533

Cleanup Site ID: 4533 Facility/Site ID: 2685 UST ID: 12024 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Custom Plywood Mill [Glossary](#)

Alternate Names: ANACORTES PLYWOOD, ANACORTES PLYWOOD INC, Anacortes Plywood Mill, CUSTOM PLYWOOD MILL

LOCATION

Address: 35TH & V ST City: ANACORTES Zip Code: 98221 County: Skagit
Latitude: 48.49390 Longitude: -122.60331 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS: 35N 2E 30

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Morman, Josh Responsible Unit: Headquarters Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ANACORTES PLYWOOD INC	Sediment	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted
ANACORTES PLYWOOD INC	Upland	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Base/Neutral/Acid Organics		R	S		S	
Bioassay Benthic Failures				C		
Halogenated Organics	C	C	S		S	
Metals Priority Pollutants	C	S	S	C	S	
Methyl tertiary-butyl ether	S	S	S		S	
Non-Halogenated Solvents	C	S	S		S	
Other Deleterious Substances				C		
Pesticides-Unspecified	S	S	S		S	
Petroleum Products-Unspecified	C	S	R	C	S	
Phenolic Compounds	S	S	S	C	S	
Polychlorinated biPhenyls (PCB)	B	S		S	S	
Polycyclic Aromatic Hydrocarbons	B	C	S	C	S	

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 4533

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		3/3/1993
VCP Opinion on Remedial Investigation Work Plan	Completed	6/3/1998	1/1/1900
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2001	8/24/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
VCP Opinion on Cleanup Action Plan	Canceled	9/10/2004	1/1/1900
VCP Status Request	Completed	11/13/2006	4/10/2007
Placement of Lien	Completed	4/2/2012	1/1/1900