

Cleanup Site ID: 4533

## Cleanup Site Details

Facility/Site ID: 2685 UST ID: 12024 Site Page Site Documents View Map

Cleanup Site ID: 4533

Cleanup Site Name: Custom Plywood Mill Glossary

Alternate Names: ANACORTES PLYWOOD, ANACORTES PLYWOOD INC, Anacortes Plywood Mill, CUSTOM PLYWOOD MILL

LOCATION

Address: 35TH & V ST City: ANACORTES Zip Code: 98221 County: Skagit

Latitude: 48.49390 Longitude: -122.60331 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS: 35N 2E 30

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? Yes

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes

Site Rank: 1 - Highest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Morman, Josh Responsible Unit: Headquarters Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
ANACORTES PLYWOOD INC	Sediment	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted
ANACORTES PLYWOOD INC	Upland	Cleanup Started	HQ	Morman, Josh	Ecology-supervised or conducted

## **ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Base/Neutral/Acid Organics		R	S		S		
Bioassay Benthic Failures				С			
Halogenated Organics	С	С	S		S		
Metals Priority Pollutants	С	S	S	С	S		
Methyl tertiary-butyl ether	S	S	S		S		
Non-Halogenated Solvents	С	S	S		S		
Other Deleterious Substances				С			
Pesticides-Unspecified	S	S	S		S		
Petroleum Products-Unspecified	С	S	R	С	S		
Phenolic Compounds	S	S	S	С	S		
Polychlorinated biPhenyls (PCB)	В	S		S	S		
Polycyclic Aromatic Hydrocarbons	В	С	S	С	S		

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

Toxics Cleanup Program Report Generated: 4/16/2024 Page 1 of 2



## Cleanup Site Details

Cleanup S	Site ID	: 4533
-----------	---------	--------

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		3/3/1993
VCP Opinion on Remedial Investigation Work Plan	Completed	6/3/1998	
Site Hazard Assessment/Federal Site Inspection	Completed	5/8/2001	8/24/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
VCP Opinion on Cleanup Action Plan	Canceled	9/10/2004	
VCP Status Request	Completed	11/13/2006	4/10/2007
Placement of Lien	Completed	4/2/2012	