

Cleanup Site Details

Cleanup Site ID: 4535

Cleanup Site ID: 4535 Facility/Site ID: 2710 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Lake Goodwin Landfill [Glossary](#)

Alternate Names: LAKE GOODWIN LANDFILL

LOCATION

Address: 18520 FRANK WATERS RD City: STANWOOD Zip Code: 98292 County: Snohomish
Latitude: 48.16626 Longitude: -122.32353 WRIA: 5 Legislative District: 10 Congressional District: 2 TRS: 31N 4E 20

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No
Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Lake Goodwin Landfill	Upland	Awaiting Cleanup	NW	Northwest Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic	C					
Conventional Contaminants, Organic	S	S				
Polychlorinated biPhenyls (PCB)	S					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment/Federal Site Inspection	Completed	10/2/2002	1/24/2003
Hazardous Sites Listing/NPL	Completed		1/24/2003
Non-LUST Ind Report Received	Completed		1/26/2011
Non-LUST Ind Report Received	Completed		4/21/2011
Non-LUST Ind Report Received	Completed		5/26/2011
Non-LUST Ind Report Received	Completed		9/8/2011
Non-LUST Ind Report Received	Completed		1/23/2012

Cleanup Site Details

Cleanup Site ID: 4535

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Non-LUST Ind Report Received	Completed		8/30/2012
Non-LUST Ind Report Received	Completed		12/6/2012
Non-LUST Ind Report Received	Completed		3/27/2013
Non-LUST Ind Report Received	Completed		6/4/2013