

Cleanup Site Details

Cleanup Site ID: 4535

Cleanup Site ID: 4535 Facility/Site ID: 2710 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Lake Goodwin Landfill Glossary

Alternate Names: LAKE GOODWIN LANDFILL

LOCATION

Address: 18520 FRANK WATERS RD City: STANWOOD Zip Code: 98292 County: Snohomish

Latitude: 48.16626 Longitude: -122.32353 WRIA: 5 Legislative District: 10 Congressional District: 2 TRS: 31N 4E 20

DETAIL

Status: Awaiting Cleanup NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 5 - Lowest Assessed Risk NFA Reason: N/A Brownfield? No

Site Manager: Northwest Region Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

 Cleanup Unit Name
 Unit Type
 Unit Status
 Resp Unit
 Unit Manager
 Current Process

 Lake Goodwin Landfill
 Upland
 Awaiting Cleanup
 NW
 Northwest Region
 No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type Restriction Media Restrictions/Requirements Date Recording Number County Tax Parcel

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

		MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Conventional Contaminants, Inorganic	С							
Conventional Contaminants, Organic	S	S						
Polychlorinated biPhenyls (PCB)	S							

Key:

B - Below Cleanup Level
S - Suspected
C - Confirmed Above Cleanup Level
R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		3/1/1988
Site Hazard Assessment	Completed	10/2/2002	1/24/2003
Hazardous Sites Listing	Completed		1/24/2003
Non-LUST Ind Report Received	Completed		1/26/2011
Non-LUST Ind Report Received	Completed		4/21/2011
Non-LUST Ind Report Received	Completed		5/26/2011
Non-LUST Ind Report Received	Completed		9/8/2011
Non-LUST Ind Report Received	Completed		1/23/2012

Toxics Cleanup Program Report Generated: 10/23/2025 Page 1 of 2



Cleanup Site Details

Cleanup Site ID: 4535

SITE ACTIVITIES							
Activity	Status	Start Date	End Date/ Completion Date				
Non-LUST Ind Report Received	Completed		8/30/2012				
Non-LUST Ind Report Received	Completed		12/6/2012				
Non-LUST Ind Report Received	Completed		3/27/2013				
Non-LUST Ind Report Received	Completed		6/4/2013				