

Cleanup Site Details

Cleanup Site ID: 4567

Cleanup Site ID: 4567 Facility/Site ID: 4755451 UST ID: 5856 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Skagit Farmers Supply Wolfkill Yard [Glossary](#)

Alternate Names: SKAGIT FARMERS SUPPLY, SKAGIT FARMERS SUPPLY MT VERNON, SKAGIT FARMERS SUPPLY WOLFKILL YARD, Wolfkill Feed & Fertilizer, WOLFKILL FEED & FERTILIZER CORP UST 5856, WOLFKILL FEED & FERTILIZER MOUNT VERNON, WOLFKILL FEED & FERTILIZER MT VERNON

LOCATION

Address: 205 W FIR ST **City:** MOUNT VERNON **Zip Code:** 98273 **County:** Skagit
Latitude: 48.42877 **Longitude:** -122.33739 **WRIA:** 3 **Legislative District:** 40 **Congressional District:** 1 **TRS:** 34N 4E 18

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 5/31/2013 **Current VCP?** No **Past VCP?** Yes
Site Rank: 5 - Lowest Assessed Risk **NFA Reason:** Voluntary Cleanup Program Review **Brownfield?** No
Site Manager: Bails, John **Responsible Unit:** Northwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WOLFKILL FEED & FERTILIZER MOUNT VERNON	Upland	No Further Action Required	NW	Bails, John	Standard Voluntary Cleanup Program

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Pesticides-Unspecified	R					
Petroleum Products-Unspecified	RB	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		3/19/1990
LUST - Notification	Completed		3/20/1990
LUST - Report Received	Completed		3/20/1990
LUST - Report Received	Completed		2/23/1999
LUST - Report Received	Completed		6/4/2002
Initial Investigation / Federal Preliminary Assessment	Completed		2/11/2009

Cleanup Site Details

Cleanup Site ID: 4567

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	3/19/2010	8/17/2010
Hazardous Sites Listing/NPL	Completed		8/17/2010
VCP Opinion on Site Cleanup	Completed	7/21/2011	10/4/2011
LUST - Report Received	Completed		11/19/2011
VCP Status Request	Completed	5/31/2012	7/10/2012
VCP Opinion on Site Cleanup	Completed	10/25/2012	1/18/2013
LUST - Report Received	Completed		2/18/2013
LUST - Report Received	Completed		5/8/2013
VCP Receipt of Plan or Report	Completed		5/8/2013
VCP Opinion on Site Cleanup	Completed	5/8/2013	5/31/2013
Site Status Changed to NFA	Completed		5/31/2013
Remove site from Hazardous Sites List	Completed		10/28/2013