

Cleanup Site Details

Cleanup Site ID: 4605

Cleanup Site ID: 4605	Facility/Site ID: 2830	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Havenwood Care Center					Glossary
Alternate Names: HAVENWOOD CARE CENTER, Marysville Care Center					

LOCATION

Address: 1821 GROVE ST			City: MARYSVILLE	Zip Code: 98270	County: Snohomish
Latitude: 48.06926	Longitude: -122.17625	WRIA: 7	Legislative District: 38	Congressional District: 2	TRS: 30N 5E 21

DETAIL

Status: No Further Action	NFA Received? Yes	Is PSI site? No
Statute: MTCA	NFA Date: 5/3/1994	Current VCP? No Past VCP? No
Site Rank: N/A	NFA Reason: Independent Remedial Action Program Review	Brownfield? No
Site Manager: Atkinson, Elaine	Responsible Unit: Northwest	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Havenwood Care Center	Upland	No Further Action Required	NW	Atkinson, Elaine	IRAP

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	R					

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		6/21/1993
Independent Report Review - Unpaid	Completed	4/25/1994	5/3/1994
Site Status Changed to NFA	Completed		5/3/1994