

Cleanup Site Details

Cleanup Site ID: 461

Cleanup Site ID: 461 **Facility/Site ID:** 1554858 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Van Stone Mine [Glossary](#)
Alternate Names: CALLAHAN MINING CORP, EQUINOX RESOURCES, EQUINOX RESOURCES INC, VAN STONE MINE, VANSTONE MINE

LOCATION

Address: 20 MILES N OF COLVILLE **City:** COLVILLE **Zip Code:** 99114 **County:** Stevens
Latitude: 48.75815 **Longitude:** -117.76053 **WRIA:** 61 **Legislative District:** 7 **Congressional District:** 5 **TRS:** 38N 40E 33

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Dowling, Brendan **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------|-----------|------------------|-----------|------------------|---------------------------------|
| VAN STONE MINE | Sediment | Awaiting Cleanup | EA | Dowling, Brendan | Ecology-supervised or conducted |
| VAN STONE MINE | Upland | Awaiting Cleanup | EA | Dowling, Brendan | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|----------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Metals Priority Pollutants | C | C | C | C | S | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|---|-----------|------------|---------------------------|
| Site Discovery/Release Report Received | Completed | | 4/30/1985 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 6/14/2001 | 11/21/2002 |
| Early Notice Letter(s) | Completed | | 9/1/2006 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 9/18/2006 | 2/21/2007 |
| Hazardous Sites Listing/NPL | Completed | | 2/21/2007 |
| Remedial Investigation and/or Feasibility Study | Completed | 7/1/2010 | 1/1/2014 |
| Emergency Action | Completed | 7/1/2012 | 10/1/2012 |
| Remedial Investigation and/or Feasibility Study | Completed | 1/1/2017 | 5/1/2017 |
| Cleanup Action Plan | Completed | 4/1/2019 | 6/16/2023 |