

Cleanup Site Details

Cleanup Site ID: 4622

Cleanup Site ID: 4622 Facility/Site ID: 75243248 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: LARSONS DRY CLEANER

[Glossary](#)

Alternate Names: LARSONS DRY CLEANER

LOCATION

Address: 501 NE 78TH ST City: VANCOUVER Zip Code: 98665 County: Clark
Latitude: 45.67844 Longitude: -122.66672 WRIA: 28 Legislative District: 49 Congressional District: 3 TRS: 2N 1E 10

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? Yes
Site Rank: 2 - Moderate-High Risk NFA Reason: N/A Brownfield? No
Site Manager: Southwest Region Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
LARSONS DRY CLEANER	Upland	Cleanup Started	SW	Southwest Region	Independent Action

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	C	C				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		11/21/2000
Initial Investigation / Federal Preliminary Assessment	Completed		2/2/2001
Site Hazard Assessment	Completed	5/11/2001	8/21/2001
Hazardous Sites Listing	Completed		8/21/2001
VCP Opinion on Remedial Investigation Work Plan	Completed	6/3/2004	3/31/2006
VCP Opinion on Remedial Investigation Work Plan	Completed	1/4/2005	3/17/2005
VCP Opinion on Cleanup Action Plan	Completed	10/31/2006	12/12/2006
VCP Opinion on Interim Action	Completed	8/6/2007	8/28/2007
VCP Receipt of Plan or Report	Completed		6/20/2011
VCP Receipt of Plan or Report	Completed		2/21/2012

Cleanup Site Details

Cleanup Site ID: 4622

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Receipt of Plan or Report	Completed		6/28/2012
VCP Receipt of Plan or Report	Completed		9/11/2013
VCP Receipt of Plan or Report	Completed		7/1/2014
VCP Receipt of Plan or Report	Completed		2/2/2015
VCP Status Request	Completed	2/27/2019	4/25/2019