

Cleanup Site Details

Cleanup Site ID: 4679

Cleanup Site ID: 4679 **Facility/Site ID:** 65663568 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Shelton Laundry & Cleaners [Glossary](#)
Alternate Names: SHELTON DRY CLEANERS, SHELTON LAUNDRY & CLEANERS

LOCATION

Address: 117 N 1ST ST **City:** SHELTON **Zip Code:** 98584 **County:** Mason
Latitude: 47.21334 **Longitude:** -123.10004 **WRIA:** 14 **Legislative District:** 35 **Congressional District:** 10 **TRS:** 20N 3W 19

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** Yes
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 2 - Moderate-High Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Balaraju, Panjini **Responsible Unit:** Southwest **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
SHELTON LAUNDRY & CLEANERS	Upland	Cleanup Started	SW	Balaraju, Panjini	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics	S	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		9/30/1997
Early Notice Letter(s)	Completed		12/30/1997
Site Hazard Assessment/Federal Site Inspection	Completed	8/8/2001	1/31/2002
Interim Action	Completed	5/1/2004	7/31/2007
Hazardous Sites Listing/NPL	Completed		12/31/2005
O & M	In Process	8/1/2007	