

Cleanup Site Details

Cleanup Site ID: 4702

Cleanup Site ID: 4702	Facility/Site ID: 16963695	UST ID: N/A	Site Page	Site Documents	View Map
Cleanup Site Name: Anacortes City					Glossary
Alternate Names: Anacortes City, CITY OF ANACORTES					

LOCATION

Address: 2ND ST & 3RD ST			City: ANACORTES	Zip Code: 98221	County: Skagit
Latitude: 48.52031	Longitude: -122.61564	WRIA: 3	Legislative District: 40	Congressional District: 2	TRS: 35N 1E 13

DETAIL

Status: Awaiting Cleanup	NFA Received? No	Is PSI site? Yes
Statute: MTCA	NFA Date: N/A	Current VCP? No Past VCP? No
Site Rank: 4 - Low-Moderate Risk	NFA Reason: N/A	Brownfield? No
Site Manager: Horne, David	Responsible Unit: Headquarters	Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Anacortes City	Sediment	Awaiting Cleanup	HQ	Headquarters	No Process
Anacortes City	Upland	Awaiting Cleanup	HQ	Horne, David	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	S	S		S		
Non-Halogenated Solvents	S	C				
Petroleum Products-Unspecified	C	C		C		

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		6/25/1996
Initial Investigation / Federal Preliminary Assessment	Completed		2/18/2000
Site Hazard Assessment	Completed	11/2/2001	2/5/2002
Hazardous Sites Listing	Completed		2/5/2002