

# Cleanup Site Details

Cleanup Site ID: 4729

Cleanup Site ID: 4729      Facility/Site ID: 2043      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Seattle Public Utilities Midway Landfill      [Glossary](#)

Alternate Names: MIDWAY LANDFILL, Seattle Public Utilities Midway Landfill

## LOCATION

Address: 24808 PACIFIC HWY S      City: KENT      Zip Code: 98032      County: King  
Latitude: 47.37951      Longitude: -122.29801      WRIA: 9      Legislative District: 33      Congressional District: 9      TRS: 22N 4E 21

## DETAIL

Status: Cleanup Complete-Active O&M/Monitoring      NFA Received? No      Is PSI site? No  
Statute: Federal - CERCLA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 0 - NPL Site (Fed HRS Score)      NFA Reason: N/A      Brownfield? No  
Site Manager: Bushnell, Tanner      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Seattle Public Utilities Midway Landfill	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	NW	Bushnell, Tanner	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic		C			C	
Conventional Contaminants, Organic		C				
Halogenated Organics		C				
Metals Priority Pollutants		C				
Polychlorinated biPhenyls (PCB)		C				

### Key:

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Remedial Investigation and/or Feasibility Study	Completed	8/16/1986	12/10/1990
Hazardous Sites Listing/NPL	Completed		9/10/1990
Site Hazard Assessment/Federal Site Inspection	Completed		9/10/1990
Cleanup Action Plan	Completed	3/15/1991	9/30/2000
Periodic Review	Completed	1/1/2005	9/1/2005

# Cleanup Site Details

Cleanup Site ID: 4729

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Periodic Review	Completed	1/1/2010	9/28/2010
Periodic Review	Completed		9/23/2015
Order/Decree/Amendment	In Process	1/27/2020	
Order/Decree/Amendment	In Process	1/27/2020	
Periodic Review	Completed	6/1/2020	8/28/2020
Periodic Review	Planned	1/1/2025	