

## **Cleanup Site Details**

Cleanup Site ID: 4755

Cleanup Site ID: 4755 Facility/Site ID: 33		39	UST ID: N/A		Site P	age <u>S</u>	Site Documents View Map				
Cleanup Site Name: Lincoln Park Landfill Glossary											
Alternate Names: LINCOLN PARK LANDFILL											
LOCATION											
Address: MISSION & CRAWFORD				City: WENATCHEE Zip Code			98801	County:	Chelan	1	
Latitude: 47.40395 Longitude: -120.30396 WRIA: 4			<b>WRIA:</b> 45	Legislative D	12 Congres	2 Congressional District: 8 TRS:					
DETAIL											
Status: No Further Action NFA Receiv			Received?	Yes		l	Is PSI site? No				
Statute: MTCA NFA Date:			Date:	9/1/1987			Current VCP? No Past VCP? No				
Site Rank: N/A NFA Reaso			Reason:	SHA, IRAP, or VCP			Brownfield? No				
Site Manager: Central Region Responsibl				Central	Active Institutional C				ontrol?	<b>N</b> o	
CLEANUP UNITS											
Cleanup Unit Name		Unit Type	Unit	Status	Resp Unit			Current Process		cess	
Lincoln Park Landfill		Upland	No Further A	ction Required	CE	Central Reg	ion	No Process			
ACTIVE INSTITUTIONAL CONTROLS											
Instrument Type Restriction Media Restriction			ictions/Requi	rements		ate Recording Number		Recordi Count		Tax Parcel	
There are no current Institutional Controls in effect for this site.											
AFFECTED MEDIA & CONTAMINANTS											
MEDIA											
Contaminant			So		water	Surface Water	Sedi	ment	Air	Bedrock	
Conventional Contaminants, Organic			S	S							
Polychlorinated biPhen	S	S									
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above   S - Suspected R - Remediated RB - Remediated-Below											
SITE ACTIVITIES											
Activity						Status		Start Date		End Date/ Completion Date	
Initial Investigation / Federal Preliminary Assessment						Completed				6/25/1985	
Site Hazard Assessment					C	Completed		6/9/1987		9/1/1987	
Site Status Changed to NFA					C	Completed		9/1/1987		/1/1987	