

Cleanup Site Details

Cleanup Site ID: 4756

Cleanup Site ID: 4756	Facility/Site ID: 340	UST ID: N/A	Site Page	Site Documents	View Map	
Cleanup Site Name: MALAGA LANDFILL					Glossary	
Alternate Names: MALAGA LANDFILL						
LOCATION						
Address: 10 MI E OF WENATCHEE		City: WENATCHEE	Zip Code: 98801	County: Chelan		
Latitude: 47.36457	Longitude: -120.15395	WRIA: 40	Legislative District: 12	Congressional District: 8	TRS: 22N 21E 25	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 1/24/1996	Current VCP? No		Past VCP? No		
Site Rank: N/A	NFA Reason: SHA, IRAP, or VCP	Brownfield? No				
Site Manager: Central Region	Responsible Unit: Central	Active Institutional Control?		No		
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
MALAGA LANDFILL	Upland	No Further Action Required	CE	Central Region	No Process	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Organics		S	S			
Metals Priority Pollutants		S	S			
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status		Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed			3/1/1988		
Site Status Changed to NFA	Completed			1/24/1996		