

Cleanup Site Details

Cleanup Site ID: 4757

Cleanup Site ID: 4757 Facility/Site ID: 357 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Pacific Pride Tanker Fire [Glossary](#)

Alternate Names: Monitor Truck Fire, PACIFIC PRIDE TANKER FIRE, Whitley Fuel Tanker Spill

LOCATION

Address: ST HWY 2 MP 116 City: MONITOR Zip Code: 98836 County: Chelan
Latitude: 47.48306 Longitude: -120.40395 WRIA: 45 Legislative District: 12 Congressional District: 8 TRS: 23N 19E 13

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 3/4/2024 Current VCP? No Past VCP? Yes
Site Rank: 3 - Moderate Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pacific Pride Tanker Fire	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Petroleum-Gasoline	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Emergency Action	Completed	7/26/1991	7/28/1991
Early Notice Letter(s)	Completed		5/18/1992
Non-LUST Ind Report Received	Completed		11/10/1993
Non-LUST Ind Report Received	Completed		2/2/1995
Non-LUST Ind Report Received	Completed		1/19/1996
Non-LUST Ind Report Received	Completed		5/13/1996
Non-LUST Ind Report Received	Completed		2/14/2003
Non-LUST Ind Report Received	Completed		11/3/2003
Non-LUST Ind Report Received	Completed		11/4/2004

Cleanup Site Details

Cleanup Site ID: 4757

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	3/21/2005	2/2/2006
Non-LUST Ind Report Received	Completed		10/31/2005
Hazardous Sites Listing/NPL	Completed		2/2/2006
Non-LUST Ind Report Received	Completed		10/23/2006
Non-LUST Ind Report Received	Completed		10/9/2007
Non-LUST Ind Report Received	Completed		10/6/2008
Non-LUST Ind Report Received	Completed		10/5/2009
Non-LUST Ind Report Received	Completed		10/14/2010
Non-LUST Ind Report Received	Completed		11/3/2011
Non-LUST Ind Report Received	Completed		10/1/2012
Non-LUST Ind Report Received	Completed		10/18/2013
VCP Receipt of Plan or Report	Completed		3/19/2015
VCP Opinion on Site Cleanup Plan	Canceled	3/19/2015	1/1/1900
VCP Status Request	Completed	1/23/2017	3/9/2017
VCP Receipt of Plan or Report	Completed		3/22/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Opinion on Site Cleanup	Canceled	5/5/2017	1/1/1900
VCP Receipt of Plan or Report	Completed		8/9/2019
VCP Status Request	Completed	10/22/2019	11/4/2019
VCP Opinion on Site Cleanup	Completed	10/29/2019	11/18/2019
VCP Receipt of Plan or Report	Completed		11/1/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		11/18/2019
Remove site from Hazardous Sites List	Completed		3/4/2024
Site Status Changed to NFA	Completed		3/4/2024