

# Cleanup Site Details

Cleanup Site ID: 4757

Cleanup Site ID: 4757      Facility/Site ID: 357      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Pacific Pride Tanker Fire      [Glossary](#)

Alternate Names: Monitor Truck Fire, PACIFIC PRIDE TANKER FIRE, Whitley Fuel Tanker Spill

## LOCATION

Address: ST HWY 2 MP 116      City: MONITOR      Zip Code: 98836      County: Chelan  
Latitude: 47.48306      Longitude: -120.40395      WRIA: 45      Legislative District: 12      Congressional District: 8      TRS: 23N 19E 13

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 3/4/2024      Current VCP? No      Past VCP? Yes  
Site Rank: 3 - Moderate Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Winslow, Frank      Responsible Unit: Central      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pacific Pride Tanker Fire	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB	RB				
Petroleum-Gasoline	RB	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Emergency Action	Completed	7/26/1991	7/28/1991
Early Notice Letter(s)	Completed		5/18/1992
Non-LUST Ind Report Received	Completed		11/10/1993
Non-LUST Ind Report Received	Completed		2/2/1995
Non-LUST Ind Report Received	Completed		1/19/1996
Non-LUST Ind Report Received	Completed		5/13/1996
Non-LUST Ind Report Received	Completed		2/14/2003
Non-LUST Ind Report Received	Completed		11/3/2003
Non-LUST Ind Report Received	Completed		11/4/2004

# Cleanup Site Details

Cleanup Site ID: 4757

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment	Completed	3/21/2005	2/2/2006
Non-LUST Ind Report Received	Completed		10/31/2005
Hazardous Sites Listing	Completed		2/2/2006
Non-LUST Ind Report Received	Completed		10/23/2006
Non-LUST Ind Report Received	Completed		10/9/2007
Non-LUST Ind Report Received	Completed		10/6/2008
Non-LUST Ind Report Received	Completed		10/5/2009
Non-LUST Ind Report Received	Completed		10/14/2010
Non-LUST Ind Report Received	Completed		11/3/2011
Non-LUST Ind Report Received	Completed		10/1/2012
Non-LUST Ind Report Received	Completed		10/18/2013
VCP Receipt of Plan or Report	Completed		3/19/2015
VCP Opinion on Site Cleanup Plan	Canceled	3/19/2015	1/1/1900
VCP Status Request	Completed	1/23/2017	3/9/2017
VCP Receipt of Plan or Report	Completed		3/22/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Receipt of Plan or Report	Completed		5/5/2017
VCP Opinion on Site Cleanup	Canceled	5/5/2017	1/1/1900
VCP Receipt of Plan or Report	Completed		8/9/2019
VCP Status Request	Completed	10/22/2019	11/4/2019
VCP Opinion on Site Cleanup	Completed	10/29/2019	11/18/2019
VCP Receipt of Plan or Report	Completed		11/1/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		11/18/2019
Remove site from Hazardous Sites List	Completed		3/4/2024
Site Status Changed to NFA	Completed		3/4/2024