

# Cleanup Site Details

Cleanup Site ID: 4765

Cleanup Site ID: 4765      Facility/Site ID: 2050      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: North Boeing Field Georgetown Steam Plant      [Glossary](#)

Alternate Names: BOEING NORTH FIELD, GEORGETOWN STEAMPLANT, North Boeing Field Georgetown Steam Plant, North Boeing Field Georgetown Steamplant, SEATTLE CITY LIGHT STEAMPLANT GEORGETOWN

## LOCATION

Address: 7370 E MARGINAL WAY S      City: SEATTLE      Zip Code: 98108      County: King  
Latitude: 47.54093      Longitude: -122.31338      WRIA: 9      Legislative District: 11      Congressional District: 9      TRS: 24N 4E 29

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 5 - Lowest Assessed Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Schwarz, Julia      Responsible Unit: Northwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
North Boeing Field Georgetown Steamplant	Upland	Cleanup Started	NW	Schwarz, Julia	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene					C	
Conventional Contaminants, Inorganic	C	C	S			
Corrosive Wastes	C	B	S			
Dioxins/Furans	S	C	S			
Halogenated Organics	C	C	S			
Halogenated Solvents					C	
Metals - Other	S	S	S			
Metals Priority Pollutants	C	C	S			
Non-Halogenated Solvents	C	C	S			
Petroleum Products-Unspecified	C	C	S			
Petroleum-Diesel					C	
Petroleum-Gasoline					C	
Petroleum-Other					C	
Polychlorinated biPhenyls (PCB)	S	C	S		S	

# Cleanup Site Details

Cleanup Site ID: 4765

**Key:**

B - Below Cleanup Level  
S - Suspected

C - Confirmed Above Cleanup Level  
R - Remediated

RA - Remediated-Above  
RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	6/15/1993	8/25/1993
Hazardous Sites Listing/NPL	Completed		8/25/1993
Site Discovery/Release Report Received	Completed		5/27/1999
Initial Investigation / Federal Preliminary Assessment	Completed		5/28/1999
Early Notice Letter(s)	Completed		9/7/1999
Site Hazard Assessment/Federal Site Inspection	Completed	9/11/2001	2/6/2001
Order/Decree/Amendment	In Process	1/1/2006	
Interim Action	Completed	5/1/2006	5/31/2006
Remedial Investigation and/or Feasibility Study	In Process	9/20/2008	
Site Hazard Assessment/Federal Site Inspection	Completed		5/16/2024