

Cleanup Site Details

Cleanup Site ID: 4765

Cleanup Site ID: 4765 Facil	ity/Site ID: 2	2050	UST ID: N/A		Site Pag	e <u>Site Do</u>	<u>cuments</u>	View Map
Cleanup Site Name: North Boeing Fie	eld Georgeto	wn Steam Plant						<u>Glossary</u>
Alternate Names: BOEING NORTH F Georgetown Steamplant, SEATTLE CI				oeing Fie	eld Georgetow	n Steam Plar	nt, North Bo	eing Field
LOCATION								
Address: 7370 E MARGINAL WAY S		С	ity: SEATTLE	2	Zip Code: 98	108 Co	unty: King	
titude: 47.54093 Longitude: -122.31338 WR		WRIA: 9 L	egislative Distr	ict: 11 Congressiona		onal District	I District: 9 TRS: 24N 4E 29	
DETAIL								
Status: Cleanup Started	NFA	Received? No)		ls F	PSI site?	No	
Statute: MTCA	NFA	Date: N/	A		Cur	rent VCP?	No Pa	st VCP? No
Site Rank: 5 - Lowest Assessed Risk	NFA	Reason: N/	A		Bro	wnfield?	No	
Site Manager: Schwarz, Julia	Resp	onsible Unit: No	orthwest		Act	ive Institutio	onal Contro	No No
CLEANUP UNITS	_							
Cleanup Unit Name	Unit Type	Unit Stat		esp Init	Unit Manager		Current Process	
North Boeing Field Georgetown Steamplant	Upland	Cleanup Sta	arted N	100	Schwarz, Julia	Ecolog	Ecology-supervised or conducted	
ACTIVE INSTITUTIONAL CONTROLS	;							
Instrument Type Restriction Media	Rest	rictions/Requirem	ents	Date	Record Num		cording county	Tax Parcel
There are no current Institutional Contro	ols in effect f	or this site.						
AFFECTED MEDIA & CONTAMINANT	ſS					-		
Contaminant		Soil	Groundwa	ter Su	MEDI.	A Sediment		
Benzene			Crounding		nuoc mutor	ocument	Δir	Bedrock
Conventional Contaminants, Inorganic							Air C	Bedrock
		С	С		S			Bedrock
Corrosive Wastes		C C	C		S			Bedrock
Corrosive Wastes Dioxins/Furans								Bedrock
		C	B		S			Bedrock
Dioxins/Furans		C S	B		S S			Bedrock
Dioxins/Furans Halogenated Organics		C S	B		S S		C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents		C S C	B C C		S S S		C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other		C S C S	B C C S		S S S S		C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other Metals Priority Pollutants		C S C S C S C	B C C C S C		S S S S S		C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other Metals Priority Pollutants Non-Halogenated Solvents		C S C C S C C C C	B C C C S C C C		S S S S S S S		C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Petroleum Products-Unspecified		C S C C S C C C C	B C C C S C C C		S S S S S S S		C C C C	Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Petroleum Products-Unspecified Petroleum-Diesel		C S C C S C C C C	B C C C S C C C		S S S S S S S		C C C C C	Bedrock Bedrock
Dioxins/Furans Halogenated Organics Halogenated Solvents Metals - Other Metals Priority Pollutants Non-Halogenated Solvents Petroleum Products-Unspecified Petroleum-Diesel Petroleum-Gasoline		C S C C S C C C C	B C C C S C C C		S S S S S S S		C C C C C C	Bedrock Bedrock



Cleanup Site Details

Key: B - Below Cleanup Level S - Suspected

C - Confirmed Above Cleanup Level R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Site Hazard Assessment	Completed	6/15/1993	8/25/1993		
Hazardous Sites Listing	Completed		8/25/1993		
Site Discovery/Release Report Received	Completed		5/27/1999		
Initial Investigation / Federal Preliminary Assessment	Completed		5/28/1999		
Early Notice Letter(s)	Completed		9/7/1999		
Site Hazard Assessment	Completed	9/11/2001	2/6/2001		
Order/Decree/Amendment	In Process	1/1/2006			
Interim Action	Completed	5/1/2006	5/31/2006		
Remedial Investigation and/or Feasibility Study	In Process	9/20/2008			
SHARP Assessment	Completed		5/16/2024		