Cleanup Site Details								Cleanup Site ID: 4768		
Cleanup Site ID: 4768 Faci	2709 <b>UST ID:</b> N/A			<u>Site Page</u>		<u>Site</u>	Site Documents View Map			
Cleanup Site Name: JH Baxter Arling								<u>Glossary</u>		
Alternate Names: JH Baxter & Co, JH Baxter Arlington, Stella Jones Co, Stella Jones Corporation										
LOCATION										
Address:   6520   188th St NE   City:   Ar					Zip	Code: 982	23	County: Sno	ohomish	
Latitude: 48.16255 Longitude: -	strict:	39 0	Congressio	nal Dist	trict: 2 TF	<b>RS</b> : 31N 5E 22				
DETAIL										
Status: Awaiting Cleanup	Received?	No			ls P	61 site?	No			
Statute: MTCA (RCRA Corrective Action) NFA Date: N/A Current VCP							P? No P	ast VCP? No		
Site Rank: 1 - Highest Assessed Risk	Reason: N/A Brownfi					vnfield	<b>?</b> No			
Site Manager: EPA Responsible Unit: EPA Active Institutional Control? No										
CLEANUP UNITS										
Cleanup Unit Name	Unit Type	Unit St	tatus	Resp Unit	Uni	Unit Manager		Current Process		
JH Baxter Arlington Upland		Awaiting Cleanup		EPA	EPA		Fe	Federal-supervised or conducted		
ACTIVE INSTITUTIONAL CONTROLS	3						,			
Instrument Type Restriction Media	Rest	trictions/Requirements			Date Recordin Numbe		-	Recording County	Tax Parcel	
There are no current Institutional Controls in effect for this site.										
AFFECTED MEDIA & CONTAMINANTS										
					MEDIA					
Contaminant	Soil		vater	ater Surface Water		Sedime	ent Air	Bedrock		
Arsenic		C								
Base/Neutral/Acid Organics	С	C		S						
Phenolic Compounds	С	С			S					
Polycyclic Aromatic Hydrocarbons	С	С		S			С			
Key:B - Below Cleanup LevelC - Confirmed Above Cleanup LevelRA - Remediated-AboveS - SuspectedR - RemediatedRB - Remediated-Below										
SITE ACTIVITIES										
Activity					Status		Start Date End Date/ Completion Da		End Date/ ompletion Date	
Site Discovery/Release Report Received				Completed				7/26/1990		
Hazardous Sites Listing				Completed			8/25/1992			
Site Hazard Assessment					Completed			8/25/1992		