

## Cleanup Site Details

Cleanup Site ID: 477

Cleanup Site ID: 477 Facility/Site ID: 76118322 UST ID: 8720 Site Page Site Documents View Map

Cleanup Site Name: Pacific Power & Light Union Gap Substation

Alternate Names: Pacific Power & Light Union Gap, Pacific Power & Light Union Gap Substation, PACIFIC POWER & LIGHT UNION GAP UST

8720, Pacific Power & Light Yakima Power

LOCATION

Address: 2718 Lower Ahtanum Rd City: Union Gap Zip Code: 98903 County: Yakima

Latitude: 46.55966 Longitude: -120.49005 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 12N 19E 6

**DETAIL** 

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? No

Site Manager: Central Region Responsible Unit: Central Active Institutional Control? No

**CLEANUP UNITS** 

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Pacific Power & Light Union Gap Substation	Upland	Cleanup Started	CE	Central Region	Independent Action

## **ACTIVE INSTITUTIONAL CONTROLS**

There are no current Institutional Controls in effect for this site.

## **AFFECTED MEDIA & CONTAMINANTS**

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel		С				
Petroleum-Other	С	С				
Polychlorinated biPhenyls (PCB)	В	В				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		1/31/2008
Early Notice Letter(s)	Completed		7/15/2008

Toxics Cleanup Program Report Generated: 7/16/2025 Page 1 of 1