

Cleanup Site Details

Cleanup Site ID: 4846

Cleanup Site ID: 4846 Facility/Site ID: 4781157 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Shell Oil Tank Farm [Glossary](#)

Alternate Names: Shell Bulk Plant, Shell Oil Tank Farm, Shell Oil Tank Farm Former

LOCATION

Address: 14TH ST & Q AVE City: ANACORTES Zip Code: 98221 County: Skagit
Latitude: 48.51128 Longitude: -122.61165 WRIA: 3 Legislative District: 40 Congressional District: 2 TRS: 35N 2E 19

DETAIL

Status: Cleanup Complete-Active O&M/Monitoring NFA Received? No Is PSI site? Yes
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Horne, David Responsible Unit: Headquarters Active Institutional Control? Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Shell Oil Tank Farm Former	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	HQ	Horne, David	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict Access, Ongoing Maintenance of Remedy, Maintain/Protect Monitoring System	5/16/2017	201705160070	Skagit	P32956

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents	C	B				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	S					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		1/12/2006
Initial Investigation / Federal Preliminary Assessment	Completed		2/17/2006
Early Notice Letter(s)	Completed		2/21/2006

Cleanup Site Details

Cleanup Site ID: 4846

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	2/28/2008	7/11/2008
Remedial Investigation and/or Feasibility Study	Completed	6/2/2008	2/3/2014
Hazardous Sites Listing/NPL	Completed		7/11/2008
Cleanup Action Plan	Completed	2/3/2013	2/3/2014
Cleanup Action - Engineering Design	Completed	2/3/2014	7/29/2014
Cleanup - Construction	Completed	9/4/2014	6/26/2015
O & M	Completed	7/14/2015	7/14/2020
Periodic Review	Completed	5/16/2017	9/20/2020
Monitoring	In Process	7/14/2020	
Periodic Review	In Process	9/20/2020	
Site Hazard Assessment/Federal Site Inspection	Completed		11/13/2024