

# Cleanup Site Details

Cleanup Site ID: 4846

Cleanup Site ID: 4846      Facility/Site ID: 4781157      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Shell Oil Tank Farm      [Glossary](#)

Alternate Names: Shell Bulk Plant, Shell Oil Tank Farm, Shell Oil Tank Farm Former

## LOCATION

Address: 14TH ST & Q AVE      City: ANACORTES      Zip Code: 98221      County: Skagit  
Latitude: 48.51128      Longitude: -122.61165      WRIA: 3      Legislative District: 40      Congressional District: 2      TRS: 35N 2E 19

## DETAIL

Status: Cleanup Complete-Active O&M/Monitoring      NFA Received? No      Is PSI site? Yes  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 3 - Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Maurer, Christopher      Responsible Unit: Headquarters      Active Institutional Control? Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Shell Oil Tank Farm Former	Upland	Cleanup Complete-Active O&M/Monitoring ongoing	HQ	Maurer, Christopher	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Groundwater, Soil	Prohibit Soil Disturbance, Restrict Access, Ongoing Maintenance of Remedy, Maintain/Protect Monitoring System	5/16/2017	201705160070	Skagit	P32956

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C				
Non-Halogenated Solvents	C	B				
Petroleum Products-Unspecified	C	C				
Polychlorinated biPhenyls (PCB)	B					
Polycyclic Aromatic Hydrocarbons	S					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Order/Decree/Amendment	In Process		
Site Discovery/Release Report Received	Completed		1/12/2006
Initial Investigation / Federal Preliminary Assessment	Completed		2/17/2006
Early Notice Letter(s)	Completed		2/21/2006

# Cleanup Site Details

Cleanup Site ID: 4846

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Hazard Assessment/Federal Site Inspection	Completed	2/28/2008	7/11/2008
Remedial Investigation and/or Feasibility Study	Completed	6/2/2008	2/3/2014
Hazardous Sites Listing/NPL	Completed		7/11/2008
Cleanup Action Plan	Completed	2/3/2013	2/3/2014
Cleanup Action - Engineering Design	Completed	2/3/2014	7/29/2014
Cleanup - Construction	Completed	9/4/2014	6/26/2015
O & M	Completed	7/14/2015	7/14/2020
Periodic Review	Completed	5/16/2017	9/20/2020
Monitoring	In Process	7/14/2020	
Periodic Review	In Process	9/20/2020	