

Cleanup Site Details

Cleanup Site ID: 4867

Cleanup Site ID: 4867 Facility/Site ID: 55763995 UST ID: N/A [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Chevron Pipe Line Company Pasco Bulk Terminal [Glossary](#)

Alternate Names: Chevron Pasco Bulk Terminal, Chevron Pipe Line Company Pasco Bulk Terminal, Chevron Pipeline Co Pasco Bulk Terminal, Chevron Pipeline Pasco Terminal, CHEVRON USA PASCO TERMINAL

LOCATION

Address: 2900 SACAJAWEA PARK RD City: PASCO Zip Code: 99301 County: Franklin
Latitude: 46.21599 Longitude: -119.02873 WRIA: 33 Legislative District: 16 Congressional District: 4 TRS: 9N 30E 35

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No
Site Manager: Loftenius, Christer Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|---|-----------|-----------------|-----------|---------------------|---------------------------------|
| Chevron Pipeline Co Pasco Bulk Terminal | Upland | Cleanup Started | EA | Loftenius, Christer | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| Contaminant | MEDIA | | | | | |
|--------------------------------|-------|-------------|---------------|----------|-----|---------|
| | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Petroleum Products-Unspecified | C | C | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/Completion Date |
|--|------------|------------|--------------------------|
| Initial Investigation / Federal Preliminary Assessment | Completed | | 12/11/2000 |
| Site Discovery/Release Report Received | Completed | | 12/11/2000 |
| Early Notice Letter(s) | Completed | | 12/12/2000 |
| Site Hazard Assessment/Federal Site Inspection | Completed | 2/13/2001 | 8/21/2001 |
| Hazardous Sites Listing/NPL | Completed | | 8/28/2001 |
| Order/Decree/Amendment | Completed | 10/1/2009 | 7/1/2015 |
| Remedial Investigation and/or Feasibility Study | Completed | 12/30/2009 | 7/15/2021 |
| Order/Decree/Amendment | Completed | 11/12/2015 | 4/18/2023 |
| Monitoring | In Process | 7/9/2017 | |

Cleanup Site Details

Cleanup Site ID: 4867

| SITE ACTIVITIES | | | |
|-------------------------------------|---------------|-------------------|--------------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Order/Decree/Amendment | In Process | 6/1/2022 | |
| Cleanup Action Plan | Completed | 7/15/2022 | 4/11/2023 |
| Cleanup Action - Engineering Design | Completed | 4/11/2023 | 1/31/2024 |
| Cleanup - Construction | In Process | 3/1/2024 | |