

Cleanup Site Details

Cleanup Site ID: 4867 Facility/Site ID: 55763995 UST ID: N/A Site Page Site Documents View Map

Cleanup Site Name: Chevron Pipe Line Company Pasco Bulk Terminal

Glossary

Cleanup Site ID: 4867

Alternate Names: Chevron Pasco Bulk Terminal, Chevron Pipe Line Company Pasco Bulk Terminal, Chevron Pipeline Co Pasco Bulk Terminal,

Chevron Pipeline Pasco Terminal, CHEVRON USA PASCO TERMINAL

LOCATION

Address: 2900 SACAJAWEA PARK RD City: PASCO Zip Code: 99301 County: Franklin

Latitude: 46.21599 Longitude: -119.02873 WRIA: 33 Legislative District: 16 Congressional District: 4 TRS: 9N 30E 35

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Loftenius, Christer Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|--|-----------|-----------------|--------------|---------------------|---------------------------------|
| Chevron Pipeline Co Pasco Bulk Terminal | Upland | Cleanup Started | EA | Loftenius, Christer | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| | Instrument Type | Restriction | Restrictions/Requirements | Date | Recording | Recording | Tax Parcel |
|---|-----------------|-------------|---------------------------|------|-----------|-----------|------------|
| ı | 71 | Media | | | Number | County | |

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|--------------------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Petroleum Products-Unspecified | С | С | | | | |

Kev.

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/ Completion Date |
|--|------------|------------|------------------------------|
| Initial Investigation / Federal Preliminary Assessment | Completed | | 12/11/2000 |
| Site Discovery/Release Report Received | Completed | | 12/11/2000 |
| Early Notice Letter(s) | Completed | | 12/12/2000 |
| Site Hazard Assessment | Completed | 2/13/2001 | 8/21/2001 |
| Hazardous Sites Listing | Completed | | 8/28/2001 |
| Order/Decree/Amendment | Completed | 10/1/2009 | 7/1/2015 |
| Remedial Investigation and/or Feasibility Study | Completed | 12/30/2009 | 7/15/2021 |
| Order/Decree/Amendment | Completed | 11/12/2015 | 4/18/2023 |
| Monitoring | In Process | 7/9/2017 | |

Toxics Cleanup Program Report Generated: 11/18/2025 Page 1 of 2



Order/Decree/Amendment

Cleanup Action - Engineering Design

Cleanup Action Plan

Cleanup - Construction

SHARP Assessment

SITE ACTIVITIES

Activity

Cleanup Site Details

Status

In Process

Completed

Completed

In Process

Completed

| Cleanup Site ID: 4867 | | | | | |
|-----------------------|------------------------------|--|--|--|--|
| Start Date | End Date/ Completion Date | | | | |
| 6/1/2022 | | | | | |
| 7/15/2022 | 4/11/2023 | | | | |
| 4/11/2023 | 1/31/2024 | | | | |

5/7/2025

3/1/2024