

# Cleanup Site Details

Cleanup Site ID: 4867

Cleanup Site ID: 4867      Facility/Site ID: 55763995      UST ID: N/A      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Chevron Pipe Line Company Pasco Bulk Terminal      [Glossary](#)

Alternate Names: Chevron Pasco Bulk Terminal, Chevron Pipe Line Company Pasco Bulk Terminal, Chevron Pipeline Co Pasco Bulk Terminal, Chevron Pipeline Pasco Terminal, CHEVRON USA PASCO TERMINAL

## LOCATION

Address: 2900 SACAJAWEA PARK RD      City: PASCO      Zip Code: 99301      County: Franklin  
Latitude: 46.21599      Longitude: -119.02873      WRIA: 33      Legislative District: 16      Congressional District: 4      TRS: 9N 30E 35

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 3 - Moderate Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Loftenius, Christer      Responsible Unit: Eastern      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Chevron Pipeline Co Pasco Bulk Terminal	Upland	Cleanup Started	EA	Loftenius, Christer	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified	C	C				

Key:  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Initial Investigation / Federal Preliminary Assessment	Completed		12/11/2000
Site Discovery/Release Report Received	Completed		12/11/2000
Early Notice Letter(s)	Completed		12/12/2000
Site Hazard Assessment/Federal Site Inspection	Completed	2/13/2001	8/21/2001
Hazardous Sites Listing/NPL	Completed		8/28/2001
Order/Decree/Amendment	Completed	10/1/2009	7/1/2015
Remedial Investigation and/or Feasibility Study	Completed	12/30/2009	7/15/2021
Order/Decree/Amendment	Completed	11/12/2015	4/18/2023
Monitoring	In Process	7/9/2017	

# Cleanup Site Details

Cleanup Site ID: 4867

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Order/Decree/Amendment	In Process	6/1/2022	
Cleanup Action Plan	Completed	7/15/2022	4/11/2023
Cleanup Action - Engineering Design	Completed	4/11/2023	1/31/2024
Cleanup - Construction	In Process	3/1/2024	