

Cleanup Site Details

Cleanup Site ID: 4891

Cleanup Site ID: 4891 Facility/Site ID: 308 UST ID: 9093 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Richland Horn Rapids Landfill [Glossary](#)

Alternate Names: HORN RAPIDS LANDFILL, RICHLAND CITY LANDFILL, Richland HHW Fire, Richland Horn Rapids Landfill, RICHLAND LANDFILL

LOCATION

Address: 3102 Twin Bridges Rd City: RICHLAND Zip Code: 99352 County: Benton
Latitude: 46.34899 Longitude: -119.33612 WRIA: 40 Legislative District: 8 Congressional District: 4 TRS: 10N 28E 17

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No
Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No
Site Rank: N/A NFA Reason: N/A Brownfield? No
Site Manager: Lemond, Luke Responsible Unit: Solid Waste Program Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HORN RAPIDS LANDFILL	Upland	Cleanup Started	SWP	Lemond, Luke	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Conventional Contaminants, Inorganic		B				
Halogenated Organics	S	C				
Petroleum-Diesel	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Hazard Assessment/Federal Site Inspection	Completed	10/22/1987	6/1/1988
Site Discovery/Release Report Received	Completed		12/17/1998
LUST - Notification	Completed		12/17/1998
LUST - Report Received	Completed		12/17/1998
Early Notice Letter(s)	Completed		3/6/2000
Order/Decree/Amendment	In Process	4/19/2016	
Remedial Investigation and/or FS Work Plan	Completed	4/28/2016	4/28/2017

Cleanup Site Details

Cleanup Site ID: 4891

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	In Process	6/9/2017	