

Cleanup Site Details

Cleanup Site ID: 4921

Cleanup Site ID: 4921 Facility/Site ID: 473 UST ID: 97621 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Kelloggs Korner [Glossary](#)

Alternate Names: ARTHUR LEYENDEKKER DBA KELLOGGS KORNER, Aurthur Leyendekker, KELLOGGS KORNER, Kelloggs Korner UST 97621

LOCATION

Address: 270 Midvale Rd City: Sunnyside Zip Code: 98944 County: Yakima
Latitude: 46.30237 Longitude: -120.02062 WRIA: 37 Legislative District: 15 Congressional District: 4 TRS: 10N 22E 35

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 5/11/2023 Current VCP? No Past VCP? Yes
Site Rank: 1 - Highest Assessed Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kelloggs Korner	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified			B			
Petroleum-Gasoline	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		4/25/1990
Site Discovery/Release Report Received	Completed		4/26/1990
Order/Decree/Amendment	Completed	8/23/1990	1/1/1900
Interim Action	Completed	8/31/1990	6/25/1991
LUST - Report Received	Completed		11/8/1990
Site Hazard Assessment	Completed	1/1/1991	6/1/1991
Remedial Investigation and/or Feasibility Study	Completed	8/16/1991	3/1/1994
Hazardous Sites Listing	Completed		8/27/1991
Routine Cleanup	Completed	3/1/1993	2/16/1993

Cleanup Site Details

Cleanup Site ID: 4921

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/24/1993
Cleanup - Construction	Completed	9/1/1993	12/15/1993
LUST - Report Received	Completed		10/27/1993
LUST - Report Received	Completed		3/3/1994
LUST - Report Received	Completed		5/12/1994
LUST - Report Received	Completed		7/20/1994
LUST - Report Received	Completed		10/8/1994
LUST - Report Received	Completed		4/25/2016
VCP Opinion on Site Cleanup	Completed	4/26/2016	8/15/2016
VCP Status Request	Completed	2/15/2018	3/15/2018
LUST - Report Received	Completed		4/12/2018
VCP Opinion on Site Cleanup	Completed	4/12/2018	4/27/2018
VCP Opinion on Site Cleanup	Completed	6/24/2019	7/29/2019
LUST - Report Received	Completed		7/1/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		7/29/2019
Remove site from Hazardous Sites List	Completed		5/11/2023
Site Status Changed to NFA	Completed		5/11/2023