

# Cleanup Site Details

Cleanup Site ID: 4921

Cleanup Site ID: 4921      Facility/Site ID: 473      UST ID: 97621      [Site Page](#)      [Site Documents](#)      [View Map](#)  
 Cleanup Site Name: Kelloggs Korner      [Glossary](#)  
 Alternate Names: ARTHUR LEYENDEKKER DBA KELLOGGS KORNER, Aurthur Leyendekker, KELLOGGS KORNER, Kelloggs Korner UST 97621

**LOCATION**  
 Address: 270 Midvale Rd      City: Sunnyside      Zip Code: 98944      County: Yakima  
 Latitude: 46.30237      Longitude: -120.02062      WRIA: 37      Legislative District: 15      Congressional District: 4      TRS: 10N 22E 35

**DETAIL**  
 Status: No Further Action      NFA Received? Yes      Is PSI site? No  
 Statute: MTCA      NFA Date: 5/11/2023      Current VCP? No      Past VCP? Yes  
 Site Rank: 1 - Highest Assessed Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
 Site Manager: Winslow, Frank      Responsible Unit: Central      Active Institutional Control? No

**CLEANUP UNITS**

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Kelloggs Korner	Upland	No Further Action Required	CE	Winslow, Frank	Standard Voluntary Cleanup

**ACTIVE INSTITUTIONAL CONTROLS**

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

**AFFECTED MEDIA & CONTAMINANTS**

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum Products-Unspecified			B			
Petroleum-Gasoline	RB	RB				

**Key:**  
 B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
 S - Suspected      R - Remediated      RB - Remediated-Below

**SITE ACTIVITIES**

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		4/25/1990
Site Discovery/Release Report Received	Completed		4/26/1990
Order/Decree/Amendment	Completed	8/23/1990	
Interim Action	Completed	8/31/1990	6/25/1991
LUST - Report Received	Completed		11/8/1990
Site Hazard Assessment/Federal Site Inspection	Completed	1/1/1991	6/1/1991
Remedial Investigation and/or Feasibility Study	Completed	8/16/1991	3/1/1994
Hazardous Sites Listing/NPL	Completed		8/27/1991
Routine Cleanup	Completed	3/1/1993	2/16/1993

# Cleanup Site Details

Cleanup Site ID: 4921

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
LUST - Report Received	Completed		3/24/1993
Cleanup - Construction	Completed	9/1/1993	12/15/1993
LUST - Report Received	Completed		10/27/1993
LUST - Report Received	Completed		3/3/1994
LUST - Report Received	Completed		5/12/1994
LUST - Report Received	Completed		7/20/1994
LUST - Report Received	Completed		10/8/1994
LUST - Report Received	Completed		4/25/2016
VCP Opinion on Site Cleanup	Completed	4/26/2016	8/15/2016
VCP Status Request	Completed	2/15/2018	3/15/2018
LUST - Report Received	Completed		4/12/2018
VCP Opinion on Site Cleanup	Completed	4/12/2018	4/27/2018
VCP Opinion on Site Cleanup	Completed	6/24/2019	7/29/2019
LUST - Report Received	Completed		7/1/2019
Petroleum Impacts to Groundwater Model Remedies	Completed		7/29/2019
Remove site from Hazardous Sites List	Completed		5/11/2023
Site Status Changed to NFA	Completed		5/11/2023