

Cleanup Site Details

Cleanup Site ID: 4922 Facility/Site ID: 477 UST ID: 9904 <u>Site Page</u> <u>Site Documents</u> <u>View Map</u>

Cleanup Site ID: 4922

Cleanup Site Name: Tiger Oil N 1st St Fmr 6013

Alternate Names: TIGER MART, Tiger Oil N 1st St Fmr 6013

LOCATION

Address: 1808 N 1ST ST City: YAKIMA Zip Code: 98902 County: Yakima

Latitude: 46.62378 Longitude: -120.51244 WRIA: 38 Legislative District: 15 Congressional District: 4 TRS: 13N 18E 12

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield? No

Site Manager: Winslow, Frank Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Tiger Mart	Upland	Cleanup Started	CE	Central Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
	ivieuia	-		number	Country	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
SHARP Assessment	Completed		
LUST - Notification	Completed		9/15/1982
Site Discovery/Release Report Received	Completed		9/16/1982
LUST - Report Received	Completed		10/27/1983
LUST - Report Received	Completed		1/1/1985
LUST - Report Received	Completed		5/9/1985
LUST - Report Received	Completed		8/21/1986
Site Hazard Assessment/Federal Site Inspection	Completed	1/15/1991	6/30/1991
LUST - Report Received	Completed		4/10/1991

Toxics Cleanup Program Report Generated: 6/7/2025 Page 1 of 2



Interim Action - Performance Monitoring

Cleanup Site Details

State of Washington	Cleanup Site Details			Cleanup Site ID: 4922			
SITE ACTIVITIES							
Activity		Status	Start Date	End Date/ Completion Date			
Hazardous Sites Listing/NPL		Completed		8/27/1991			
LUST - Report Received		Completed		3/2/2015			
LUST - Report Received		Completed		3/31/2015			
LUST - Report Received		Completed		5/21/2015			
LUST - Report Received		Completed		8/4/2016			
LUST - Report Received		Completed		5/25/2017			
LUST - Report Received		Completed		6/19/2017			
Order/Decree/Amendment		In Process	9/30/2019				
Interim Action - Construction		Completed	8/22/2022	8/31/2023			

In Process

1/1/2023