

Cleanup Site Details

Cleanup Site ID: 4922

Cleanup Site ID: 4922 **Facility/Site ID:** 477 **UST ID:** 9904 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Tiger Oil N 1st St Fmr 6013 [Glossary](#)
Alternate Names: TIGER MART, Tiger Oil N 1st St Fmr 6013

LOCATION

Address: 1808 N 1ST ST **City:** YAKIMA **Zip Code:** 98902 **County:** Yakima
Latitude: 46.62378 **Longitude:** -120.51244 **WRIA:** 38 **Legislative District:** 15 **Congressional District:** 4 **TRS:** 13N 18E 12

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Winslow, Frank **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Tiger Mart	Upland	Cleanup Started	CE	Central Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	C	C				
Petroleum-Gasoline	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		9/15/1982
Site Discovery/Release Report Received	Completed		9/16/1982
LUST - Report Received	Completed		10/27/1983
LUST - Report Received	Completed		1/1/1985
LUST - Report Received	Completed		5/9/1985
LUST - Report Received	Completed		8/21/1986
Site Hazard Assessment/Federal Site Inspection	Completed	1/15/1991	6/30/1991
LUST - Report Received	Completed		4/10/1991
Hazardous Sites Listing/NPL	Completed		8/27/1991

Cleanup Site Details

Cleanup Site ID: 4922

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		3/2/2015
LUST - Report Received	Completed		3/31/2015
LUST - Report Received	Completed		5/21/2015
LUST - Report Received	Completed		8/4/2016
LUST - Report Received	Completed		5/25/2017
LUST - Report Received	Completed		6/19/2017
Order/Decree/Amendment	In Process	9/30/2019	
Interim Action - Construction	Completed	8/22/2022	8/31/2023
Interim Action - Performance Monitoring	In Process	1/1/2023	