

Cleanup Site Details

Cleanup Site ID: 4922 Facility/Site ID: 477 **UST ID: 9904** Site Page **Site Documents** View Map

Cleanup Site ID: 4922

Cleanup Site Name: Tiger Oil N 1st St Fmr 6013 **Glossary**

Alternate Names: TIGER MART, Tiger Oil N 1st St Fmr 6013

LOCATION

Address: 1808 N 1ST ST City: YAKIMA **Zip Code:** 98902 County: Yakima

Latitude: 46.62378 Longitude: -120.51244 **WRIA**: 38 Legislative District: 15 Congressional District: 4 **TRS**: 13N 18E 12

DETAIL

NFA Received? Is PSI site? Status: No No Cleanup Started

MTCA NFA Date: Current VCP? Past VCP? No Statute: N/A No

Site Rank: 3 - Moderate Risk NFA Reason: N/A Brownfield?

Site Manager: Winslow, Frank Responsible Unit: Central **Active Institutional Control?** No

CLEANUP UNITS

Resp **Cleanup Unit Name Unit Type Unit Status Unit Manager Current Process** Unit Tiger Mart Upland Cleanup Started CE Central Region Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Restriction Recording Recording Instrument Type Tax Parcel Restrictions/Requirements Date Media Number County

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Diesel	С	С				
Petroleum-Gasoline	С	С				

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/15/1982
Site Discovery/Release Report Received	Completed		9/16/1982
LUST - Report Received	Completed		10/27/1983
LUST - Report Received	Completed		1/1/1985
LUST - Report Received	Completed		5/9/1985
LUST - Report Received	Completed		8/21/1986
Site Hazard Assessment	Completed	1/15/1991	6/30/1991
LUST - Report Received	Completed		4/10/1991
Hazardous Sites Listing	Completed		8/27/1991

Toxics Cleanup Program Report Generated: 11/18/2025 Page 1 of 2



SHARP Assessment

Cleanup Site Details

ECOLOGY State of Washington	Cleanup Site D	Cleanup Site ID: 4922		
SITE ACTIVITIES				
Activity		Status	Start Date	End Date/ Completion Date
LUST - Report Received		Completed		3/2/2015
LUST - Report Received		Completed		3/31/2015
LUST - Report Received		Completed		5/21/2015
LUST - Report Received		Completed		8/4/2016
LUST - Report Received		Completed		5/25/2017
LUST - Report Received		Completed		6/19/2017
Order/Decree/Amendment		In Process	9/30/2019	
Interim Action - Construction		Completed	8/22/2022	8/31/2023
Interim Action - Performance Monitoring		In Process	1/1/2023	

Completed

3/19/2024