

Cleanup Site Details

Cleanup Site ID: 4927

Cleanup Site ID: 4927 **Facility/Site ID:** 502 **UST ID:** 200130 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Hahn Motor Company [Glossary](#)
Alternate Names: Hahn Motor Company

LOCATION

Address: 1201 S 1ST ST **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.58876 **Longitude:** -120.49842 **WRIA:** 37 **Legislative District:** 14 **Congressional District:** 4 **TRS:** 13N 19E 30

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** Yes **Past VCP?** Yes
Site Rank: 3 - Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Wise, Tavi **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HAHN MOTOR COMPANY	Upland	Cleanup Started	CE	Wise, Tavi	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	C	C				
Petroleum-Diesel	C	C				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Report Received	Completed		1/3/1990
LUST - Notification	Completed		1/30/1990
Site Hazard Assessment/Federal Site Inspection	Completed	1/1/1991	4/1/1991
Hazardous Sites Listing/NPL	Completed		3/12/1991
Remedial Investigation and/or Feasibility Study	Canceled	8/1/1993	4/1/1999
VCP Opinion on Site Cleanup	Completed	1/25/2016	2/23/2016
LUST - Report Received	Completed		3/23/2022
LUST - Report Received	Completed		8/8/2022
VCP Receipt of Plan or Report	Completed		8/16/2022

Cleanup Site Details

Cleanup Site ID: 4927

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/7/2022
VCP Opinion on Site Cleanup	Completed	11/7/2022	3/14/2023
VCP Receipt of Plan or Report	Completed		3/1/2023
LUST - Report Received	Completed		3/1/2023
LUST - Report Received	Completed		4/26/2023
LUST - Report Received	Completed		7/13/2023
VCP Opinion on Site Cleanup	Completed	10/6/2023	1/12/2024
LUST - Report Received	Completed		10/13/2023
LUST - Report Received	Completed		2/20/2024