

Cleanup Site Details

Cleanup Site ID: 4927

Cleanup Site ID: 4927 Facility/Site ID: 502 UST ID: 200130 Site Page Site Documents View Map

Cleanup Site Name: Hahn Motor Company

Alternate Names: Hahn Motor Company

LOCATION

Address: 1201 S 1ST ST City: YAKIMA Zip Code: 98901 County: Yakima

Latitude: 46.58876 Longitude: -120.49842 WRIA: 37 Legislative District: 14 Congressional District: 4 TRS: 13N 19E 30

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No

Statute: MTCA NFA Date: 4/2/2025 Current VCP? No Past VCP? Yes

Site Rank: 3 - Moderate Risk NFA Reason: Voluntary Cleanup Program Review Brownfield? No

Site Manager: Wise, Tavi Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Hahn Motor Company	Upland	No Further Action Required	CE	Wise, Tavi	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction	Restrictions/Requirements	Date	Recording	Recording	Tax Parcel
	Media	The state of the s		Number	County	

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA					
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	RB	RB				
Petroleum-Diesel	RB	RB				

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level S - Suspected R - Remediated

RA - Remediated-Above RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/3/1990
LUST - Notification	Completed		1/30/1990
Site Hazard Assessment	Completed	1/1/1991	4/1/1991
Hazardous Sites Listing	Completed		3/12/1991
Remedial Investigation and/or Feasibility Study	Canceled	8/1/1993	4/1/1999
VCP Opinion on Site Cleanup	Completed	1/25/2016	2/23/2016
LUST - Report Received	Completed		3/23/2022
LUST - Report Received	Completed		8/8/2022
VCP Receipt of Plan or Report	Completed		8/16/2022

Toxics Cleanup Program Report Generated: 11/8/2025 Page 1 of 2



Cleanup Site Details

SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Report Received	Completed		11/7/2022			
VCP Opinion on Site Cleanup	Completed	11/7/2022	3/14/2023			
VCP Receipt of Plan or Report	Completed		3/1/2023			
LUST - Report Received	Completed		3/1/2023			
LUST - Report Received	Completed		4/26/2023			
LUST - Report Received	Completed		7/13/2023			
VCP Opinion on Site Cleanup	Completed	10/6/2023	1/12/2024			
LUST - Report Received	Completed		10/13/2023			
LUST - Report Received	Completed		2/20/2024			
LUST - Report Received	Completed		5/28/2024			
LUST - Report Received	Completed		6/17/2024			
VCP Receipt of Plan or Report	Completed		8/19/2024			
VCP Opinion on Remedial Investigation	Completed	11/15/2024	4/2/2025			
Remove site from Hazardous Sites List	Completed		4/2/2025			
Site Status Changed to NFA	Completed		4/2/2025			