

# Cleanup Site Details

Cleanup Site ID: 4927

Cleanup Site ID: 4927      Facility/Site ID: 502      UST ID: 200130      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Hahn Motor Company

[Glossary](#)

Alternate Names: Hahn Motor Company

## LOCATION

Address: 1201 S 1ST ST      City: YAKIMA      Zip Code: 98901      County: Yakima  
Latitude: 46.58876      Longitude: -120.49842      WRIA: 37      Legislative District: 14      Congressional District: 4      TRS: 13N 19E 30

## DETAIL

Status: No Further Action      NFA Received? Yes      Is PSI site? No  
Statute: MTCA      NFA Date: 4/2/2025      Current VCP? No      Past VCP? Yes  
Site Rank: 3 - Moderate Risk      NFA Reason: Voluntary Cleanup Program Review      Brownfield? No  
Site Manager: Wise, Tavi      Responsible Unit: Central      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Hahn Motor Company	Upland	No Further Action Required	CE	Wise, Tavi	Standard Voluntary Cleanup

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

### MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	RB	RB				
Petroleum-Diesel	RB	RB				

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		1/3/1990
LUST - Notification	Completed		1/30/1990
Site Hazard Assessment	Completed	1/1/1991	4/1/1991
Hazardous Sites Listing	Completed		3/12/1991
Remedial Investigation and/or Feasibility Study	Canceled	8/1/1993	4/1/1999
VCP Opinion on Site Cleanup	Completed	1/25/2016	2/23/2016
LUST - Report Received	Completed		3/23/2022
LUST - Report Received	Completed		8/8/2022
VCP Receipt of Plan or Report	Completed		8/16/2022

# Cleanup Site Details

Cleanup Site ID: 4927

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		11/7/2022
VCP Opinion on Site Cleanup	Completed	11/7/2022	3/14/2023
VCP Receipt of Plan or Report	Completed		3/1/2023
LUST - Report Received	Completed		3/1/2023
LUST - Report Received	Completed		4/26/2023
LUST - Report Received	Completed		7/13/2023
VCP Opinion on Site Cleanup	Completed	10/6/2023	1/12/2024
LUST - Report Received	Completed		10/13/2023
LUST - Report Received	Completed		2/20/2024
LUST - Report Received	Completed		5/28/2024
LUST - Report Received	Completed		6/17/2024
VCP Receipt of Plan or Report	Completed		8/19/2024
VCP Opinion on Remedial Investigation	Completed	11/15/2024	4/2/2025
Remove site from Hazardous Sites List	Completed		4/2/2025
Site Status Changed to NFA	Completed		4/2/2025