

Cleanup Site Details

Cleanup Site ID: 4937

Cleanup Site ID: 4937 **Facility/Site ID:** 528 **UST ID:** 9856 [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: Tiger Oil 16th St & E Nob Hill [Glossary](#)
Alternate Names: CHARLES CONLEY, Tiger Oil 16th St & E Nob Hill, TIGER OIL CORPORATION, TIGER OIL CORPORATION UST 9856

LOCATION

Address: 1606 E NOB HILL BLVD **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.58469 **Longitude:** -120.47940 **WRIA:** 37 **Legislative District:** 15 **Congressional District:** 4 **TRS:** 13N 19E 29

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 3/4/2016 **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No
Site Manager: Monahan, Mary **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Tiger Oil Corporation	Upland	No Further Action Required	CE	Monahan, Mary	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Gasoline	RB	RB				

Key:
 B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
 S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		5/11/1989
LUST - Report Received	Completed		5/11/1989
Early Notice Letter(s)	Completed		12/30/1992
Hazardous Sites Listing/NPL	Completed		3/9/1993
Remedial Investigation and/or Feasibility Study	Canceled	3/9/1993	6/1/1998
LUST - Report Received	Completed		2/25/2015
LUST - Report Received	Completed		3/31/2015
LUST - Report Received	Completed		7/1/2015
LUST - Report Received	Completed		7/1/2015

Cleanup Site Details

Cleanup Site ID: 4937

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remove site from Hazardous Sites List	Completed		3/4/2016
Site Status Changed to NFA	Completed		3/4/2016