

Cleanup Site Details

Cleanup Site ID: 4944

Cleanup Site ID: 4944	Facility/Site ID: 543	UST ID: 503227	Site Page	Site Documents	View Map
Cleanup Site Name: Tidricks Quality Transmission Inc					Glossary
Alternate Names: CARLOS MOTORS, TIDRIC QUALITY TRANSMISSION, TIDRICKS QUALITY TRANSMISSION, Tidricks Quality Transmission Inc					

LOCATION					
Address: 1802 S 1ST ST	City: YAKIMA	Zip Code: 98903	County: Yakima		
Latitude: 46.57729	Longitude: -120.49230	WRIA: 37	Legislative District: 14	Congressional District: 4	TRS: 13N 19E 31

DETAIL					
Status: No Further Action	NFA Received? Yes	Is PSI site? No			
Statute: MTCA	NFA Date: 9/18/2015	Current VCP? No	Past VCP? No		
Site Rank: 1 - Highest Assessed Risk	NFA Reason: Ecology Supervised/Conducted Cleanup	Brownfield? No			
Site Manager: Mefford, John	Responsible Unit: Central	Active Institutional Control? No			

CLEANUP UNITS					
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Carlos Motors	Upland	No Further Action Required	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB					
Metals Priority Pollutants	RB					
Non-Halogenated Solvents	RB					
Petroleum-Other	RB					
Polycyclic Aromatic Hydrocarbons	RB					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		4/20/1993
Initial Investigation / Federal Preliminary Assessment	Completed		1/15/1994
Site Hazard Assessment/Federal Site Inspection	Completed		6/30/1994
Hazardous Sites Listing/NPL	Completed		8/23/1994
LUST - Notification	Completed		7/6/1999

Cleanup Site Details

Cleanup Site ID: 4944

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		7/6/1999
Early Notice Letter(s)	Completed		7/24/2012
Early Notice Letter(s)	Completed		8/8/2012
Remedial Investigation and/or FS Work Plan	Completed	11/22/2013	4/16/2014
Remedial Investigation and/or Feasibility Study	Completed	4/18/2014	5/27/2015
Remedial Investigation and/or Feasibility Study	Completed	8/21/2015	8/26/2015
Remove site from Hazardous Sites List	Completed		9/4/2015
Order/Decree/Amendment	Completed		9/18/2015
Site Status Changed to NFA	Completed		9/18/2015