

Cleanup Site Details

Cleanup Site ID: 4944

Cleanup Site ID: 4944 Facility/Site ID: 543 UST ID: 503227 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Tidricks Quality Transmission Inc

[Glossary](#)

Alternate Names: CARLOS MOTORS, TIDRIC QUALITY TRANSMISSION, TIDRICKS QUALITY TRANSMISSION, Tidricks Quality Transmission Inc

LOCATION

Address: 1802 S 1ST ST City: YAKIMA Zip Code: 98903 County: Yakima
Latitude: 46.57729 Longitude: -120.49230 WRIA: 37 Legislative District: 14 Congressional District: 4 TRS: 13N 19E 31

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 9/18/2015 Current VCP? No Past VCP? No
Site Rank: 1 - Highest Assessed Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Mefford, John Responsible Unit: Central Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Carlos Motors	Upland	No Further Action Required	CE	Mefford, John	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Lead	RB					
Metals Priority Pollutants	RB					
Non-Halogenated Solvents	RB					
Petroleum-Other	RB					
Polycyclic Aromatic Hydrocarbons	RB					

Key:

B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
Site Discovery/Release Report Received	Completed		4/20/1993
Initial Investigation / Federal Preliminary Assessment	Completed		1/15/1994
Site Hazard Assessment/Federal Site Inspection	Completed		6/30/1994
Hazardous Sites Listing/NPL	Completed		8/23/1994
LUST - Notification	Completed		7/6/1999

Cleanup Site Details

Cleanup Site ID: 4944

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
LUST - Report Received	Completed		7/6/1999
Early Notice Letter(s)	Completed		7/24/2012
Early Notice Letter(s)	Completed		8/8/2012
Remedial Investigation and/or FS Work Plan	Completed	11/22/2013	4/16/2014
Remedial Investigation and/or Feasibility Study	Completed	4/18/2014	5/27/2015
Remedial Investigation and/or Feasibility Study	Completed	8/21/2015	8/26/2015
Remove site from Hazardous Sites List	Completed		9/4/2015
Order/Decree/Amendment	Completed		9/18/2015
Site Status Changed to NFA	Completed		9/18/2015