

Cleanup Site Details

Cleanup Site ID: 4945

Cleanup Site ID: 4945 Facility/Site ID: 545 UST ID: 7786 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Washington Central Railroad Roundhouse

[Glossary](#)

Alternate Names: COLUMBIA BASIN RAILROAD CO YAKIMA, RAILROAD ROUNDHOUSE, UNION PACIFIC RAILROAD UST 7786, UPRR YAKIMA, Washington Central Railroad Roundhouse

LOCATION

Address: 6 E ARLINGTON **City:** YAKIMA **Zip Code:** 98901 **County:** Yakima
Latitude: 46.58879 **Longitude:** -120.50413 **WRIA:** 37 **Legislative District:** 14 **Congressional District:** 4 **TRS:** 13N 19E 30

DETAIL

Status: No Further Action **NFA Received?** Yes **Is PSI site?** No
Statute: MTCA **NFA Date:** 4/28/2018 **Current VCP?** No **Past VCP?** No
Site Rank: 1 - Highest Assessed Risk **NFA Reason:** Ecology Supervised/Conducted Cleanup **Brownfield?** No
Site Manager: Parker, Kyle **Responsible Unit:** Central **Active Institutional Control?** No

CLEANUP UNITS

| Cleanup Unit Name | Unit Type | Unit Status | Resp Unit | Unit Manager | Current Process |
|-------------------------------|-----------|----------------------------|-----------|--------------|---------------------------------|
| UNION PACIFIC RAILROAD TANK 4 | Upland | No Further Action Required | CE | Parker, Kyle | Ecology-supervised or conducted |

ACTIVE INSTITUTIONAL CONTROLS

| Instrument Type | Restriction Media | Restrictions/Requirements | Date | Recording Number | Recording County | Tax Parcel |
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|
|-----------------|-------------------|---------------------------|------|------------------|------------------|------------|

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

| MEDIA | | | | | | |
|----------------------|------|-------------|---------------|----------|-----|---------|
| Contaminant | Soil | Groundwater | Surface Water | Sediment | Air | Bedrock |
| Halogenated Solvents | B | | | | | |
| Lead | B | | | | | |
| Petroleum-Diesel | RB | | | | | |

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

| Activity | Status | Start Date | End Date/Completion Date |
|---|-----------|------------|--------------------------|
| LUST - Notification | Completed | | 9/13/1989 |
| LUST - Report Received | Completed | | 11/13/1989 |
| LUST - Report Received | Completed | | 8/16/1996 |
| LUST - Site Assessment Report | Completed | | 8/16/1996 |
| Hazardous Sites Listing/NPL | Completed | | 12/31/1996 |
| Remedial Investigation and/or Feasibility Study | Canceled | 9/30/1997 | 4/20/1998 |
| Remove site from Hazardous Sites List | Completed | | 4/28/2018 |

Cleanup Site Details

Cleanup Site ID: 4945

| SITE ACTIVITIES | | | |
|----------------------------|-----------|------------|------------------------------|
| Activity | Status | Start Date | End Date/ Completion Date |
| Site Status Changed to NFA | Completed | | 4/28/2018 |