

# Cleanup Site Details

Cleanup Site ID: 4945

Cleanup Site ID: 4945      Facility/Site ID: 545      UST ID: 7786      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Washington Central Railroad Roundhouse      [Glossary](#)

**Alternate Names:** COLUMBIA BASIN RAILROAD CO YAKIMA, RAILROAD ROUNDHOUSE, UNION PACIFIC RAILROAD UST 7786, UPRR YAKIMA, Washington Central Railroad Roundhouse

## LOCATION

**Address:** 6 E ARLINGTON      **City:** YAKIMA      **Zip Code:** 98901      **County:** Yakima  
**Latitude:** 46.58879      **Longitude:** -120.50413      **WRIA:** 37      **Legislative District:** 14      **Congressional District:** 4      **TRS:** 13N 19E 30

## DETAIL

**Status:** No Further Action      **NFA Received?** Yes      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** 4/28/2018      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** 1 - Highest Assessed Risk      **NFA Reason:** Ecology Supervised/Conducted Cleanup      **Brownfield?** No  
**Site Manager:** Parker, Kyle      **Responsible Unit:** Central      **Active Institutional Control?** No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
UNION PACIFIC RAILROAD TANK 4	Upland	No Further Action Required	CE	Parker, Kyle	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Halogenated Solvents	B					
Lead	B					
Petroleum-Diesel	RB					

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		9/13/1989
LUST - Report Received	Completed		11/13/1989
LUST - Report Received	Completed		8/16/1996
LUST - Site Assessment Report	Completed		8/16/1996
Hazardous Sites Listing/NPL	Completed		12/31/1996
Remedial Investigation and/or Feasibility Study	Canceled	9/30/1997	4/20/1998
Remove site from Hazardous Sites List	Completed		4/28/2018

# Cleanup Site Details

Cleanup Site ID: 4945

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Status Changed to NFA	Completed		4/28/2018