

Cleanup Site Details

Cleanup Site ID: 4953

Cleanup Site ID: 4953 Facility/Site ID: 611 UST ID: 11494 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Moses Lake City Maint Facility [Glossary](#)

Alternate Names: Moses Lake City Maint Facility, MOSES LAKE CITY OF , MOSES LAKE CITY UST 11494

LOCATION

Address: 835 E PENN ST City: MOSES LAKE Zip Code: 98837 County: Grant
Latitude: 47.13215 Longitude: -119.26383 WRIA: 41 Legislative District: 13 Congressional District: 4 TRS: 19N 28E 14

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 7/26/2007 Current VCP? No Past VCP? No
Site Rank: 2 - Moderate-High Risk NFA Reason: Ecology Supervised/Conducted Cleanup Brownfield? No
Site Manager: Treccani, Sandra Responsible Unit: Eastern Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
MOSES LAKE CITY OF OPERATIONS FACILITY	Upland	No Further Action Required	EA	Eastern Region	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Petroleum-Other	RB	RB				

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
LUST - Notification	Completed		9/25/1990
Initial Investigation / Federal Preliminary Assessment	Completed		10/10/1990
Early Notice Letter(s)	Completed		10/22/1990
LUST - Report Received	Completed		6/9/1992
Site Hazard Assessment/Federal Site Inspection	Completed	2/11/1993	6/2/1993
Hazardous Sites Listing/NPL	Completed		8/24/1993
LUST - Report Received	Completed		6/28/1996
LUST - Report Received	Completed		10/21/1996
LUST - Report Received	Completed		5/1/1997

Cleanup Site Details

Cleanup Site ID: 4953

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Remedial Investigation and/or Feasibility Study	Completed	9/16/2002	1/30/2004
Cleanup Action Plan	Completed	2/2/2004	10/1/2004
Cleanup Action - Engineering Design	Completed	10/1/2004	6/13/2005
Cleanup - Construction	Completed	6/15/2005	11/4/2005
O & M	Completed	11/4/2005	4/1/2007
Remove site from Hazardous Sites List	Completed		7/26/2007
Site Status Changed to NFA	Completed		7/26/2007