

# Cleanup Site Details

Cleanup Site ID: 4987

Cleanup Site ID: 4987      Facility/Site ID: 1126      UST ID: 10407      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Weyerhaeuser Sawmill Aberdeen/Seaport Landing      [Glossary](#)

**Alternate Names:** WEYERHAEUSER ABERDEEN SAWMILL, WEYERHAEUSER COMPANY ABERDEEN, WEYERHAEUSER SAWMILL, Weyerhaeuser Sawmill Aberdeen, Weyerhaeuser Sawmill Aberdeen/Seaport Landing

## LOCATION

**Address:** 500 N CUSTER ST      **City:** ABERDEEN      **Zip Code:** 98520      **County:** Grays Harbor

**Latitude:** 46.97263      **Longitude:** -123.80046      **WRIA:** 22      **Legislative District:** 19      **Congressional District:** 6      **TRS:**

## DETAIL

**Status:** Cleanup Started      **NFA Received?** No      **Is PSI site?** No  
**Statute:** MTCA      **NFA Date:** N/A      **Current VCP?** No      **Past VCP?** No  
**Site Rank:** N/A      **NFA Reason:** N/A      **Brownfield?** Yes  
**Site Manager:** Middleton, Tom      **Responsible Unit:** Southwest      **Active Institutional Control?** Yes

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WEYERHAEUSER CO	Upland	Awaiting Cleanup	SW	Middleton, Tom	Ecology-supervised or conducted
WEYERHAEUSER SAWMILL ABERDEEN - Sediments	Sediment	Cleanup Started	SW	Mercuri, Joyce	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prevent the Reuse or Relocation of Site Soil	4/3/1998	980406028	Grays Harbor	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans				C		
Mercury				C		
Metals Priority Pollutants	R	C				
Other Deleterious Substances				C		
Other Non-Halogenated Organics				C		
Petroleum-Diesel				C		
Petroleum-Other	C	C		C		
Phenolic Compounds	R	C		C		
Polycyclic Aromatic Hydrocarbons				C		

**Key:**  
B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

# Cleanup Site Details

Cleanup Site ID: 4987

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Site Discovery/Release Report Received	Completed		11/26/1990
LUST - Notification	Completed		8/2/1993
LUST - Report Received	Completed		8/2/1993
Site Status Changed to NFA	Completed		2/8/1999
Site Hazard Assessment/Federal Site Inspection	Canceled	1/1/2005	12/31/2006
Reopen Site	Completed		7/24/2014
Remedial Investigation and/or FS Work Plan	Completed	1/26/2015	6/12/2015
Preparatory Action	Completed	2/4/2015	3/5/2015
Order/Decree/Amendment	Canceled	3/5/2015	6/15/2015
Order/Decree/Amendment	In Process	5/25/2018	
Remedial Investigation and/or FS Work Plan	Completed	4/1/2019	11/6/2019
Remedial Investigation and/or FS Work Plan	Completed	5/1/2019	12/2/2019
Remedial Investigation and/or Feasibility Study	In Process	8/31/2019	