

Cleanup Site Details

Cleanup Site ID: 4987

Cleanup Site ID: 4987 Facility/Site ID: 1126 UST ID: 10407 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Weyerhaeuser Sawmill Aberdeen/Seaport Landing [Glossary](#)

Alternate Names: WEYERHAEUSER ABERDEEN SAWMILL, WEYERHAEUSER COMPANY ABERDEEN, WEYERHAEUSER SAWMILL, Weyerhaeuser Sawmill Aberdeen, Weyerhaeuser Sawmill Aberdeen/Seaport Landing

LOCATION

Address: 500 N CUSTER ST **City:** ABERDEEN **Zip Code:** 98520 **County:** Grays Harbor
Latitude: 46.97263 **Longitude:** -123.80046 **WRIA:** 22 **Legislative District:** 19 **Congressional District:** 6 **TRS:** 17N 9W 9

DETAIL

Status: Cleanup Started **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: N/A **NFA Reason:** N/A **Brownfield?** Yes
Site Manager: Middleton, Tom **Responsible Unit:** Southwest **Active Institutional Control?** Yes

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WEYERHAEUSER CO	Upland	Awaiting Cleanup	SW	Middleton, Tom	Ecology-supervised or conducted
WEYERHAEUSER SAWMILL ABERDEEN - Sediments	Sediment	Cleanup Started	SW	Mercuri, Joyce	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
Environmental Covenant	Soil, Groundwater	Restrict Land Use, Restrict All Ground Water Extraction/Well Installation, Prevent the Reuse or Relocation of Site Soil	4/3/1998	980406028	Grays Harbor	

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the [Environmental Covenants Registry List](#).

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Dioxins/Furans				C		
Mercury				C		
Metals Priority Pollutants	R	C				
Other Deleterious Substances				C		
Other Non-Halogenated Organics				C		
Petroleum-Diesel				C		
Petroleum-Other	C	C		C		
Phenolic Compounds	R	C		C		
Polycyclic Aromatic Hydrocarbons				C		

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

Cleanup Site Details

Cleanup Site ID: 4987

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/26/1990
LUST - Notification	Completed		8/2/1993
LUST - Report Received	Completed		8/2/1993
Site Status Changed to NFA	Completed		2/8/1999
Site Hazard Assessment/Federal Site Inspection	Canceled	1/1/2005	12/31/2006
Reopen Site	Completed		7/24/2014
Remedial Investigation and/or FS Work Plan	Completed	1/26/2015	6/12/2015
Preparatory Action	Completed	2/4/2015	3/5/2015
Order/Decree/Amendment	Canceled	3/5/2015	6/15/2015
Order/Decree/Amendment	In Process	5/25/2018	
Remedial Investigation and/or FS Work Plan	Completed	4/1/2019	11/6/2019
Remedial Investigation and/or FS Work Plan	Completed	5/1/2019	12/2/2019
Remedial Investigation and/or Feasibility Study	In Process	8/31/2019	