

Cleanup Site ID: 4987

Cleanup Site Details

Facility/Site ID: 1126 UST ID: 10407 Site Page Site Documents View Map

Cleanup Site Name: Weyerhaeuser Sawmill Aberdeen/Seaport Landing

Glossary

Cleanup Site ID: 4987

Alternate Names: WEYERHAEUSER ABERDEEN SAWMILL, WEYERHAEUSER COMPANY ABERDEEN, WEYERHAEUSER SAWMILL,

Weyerhaeuser Sawmill Aberdeen, Weyerhaeuser Sawmill Aberdeen/Seaport Landing

LOCATION

Address: 500 N CUSTER ST City: ABERDEEN Zip Code: 98520 County: Grays Harbor

Latitude: 46.97263 Longitude: -123.80046 WRIA: 22 Legislative District: 19 Congressional District: 6 TRS: 17N 9W 9

DETAIL

Status: Cleanup Started NFA Received? No Is PSI site? No

Statute: MTCA NFA Date: N/A Current VCP? No Past VCP? No

Site Rank: N/A NFA Reason: N/A Brownfield? Yes

Site Manager: Middleton, Tom Responsible Unit: Southwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
WEYERHAEUSER CO	Upland	Cleanup Started	SW	Middleton, Tom	Ecology-supervised or conducted
WEYERHAEUSER SAWMILL ABERDEEN - Sediments	Sediment	Cleanup Started	sw	Mercuri, Joyce	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	----------------------	---------------------------	------	---------------------	---------------------	------------

There are no current Institutional Controls in effect for this site.

Institutional Control documents may be available under the 'Site Documents' link at the top of the page. For more details on Institutional Controls, please see the **Environmental Covenants Registry List**.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA							
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock		
Dioxins/Furans				С				
Mercury				С				
Metals Priority Pollutants	R	С						
Other Deleterious Substances				С				
Other Non-Halogenated Organics				С				
Petroleum-Diesel				С				
Petroleum-Other	С	С		С				
Phenolic Compounds	R	С		С				
Polycyclic Aromatic Hydrocarbons				С				

Key:

B - Below Cleanup Level C -

Toxics Cleanup Program

C - Confirmed Above Cleanup Level

RA - Remediated-Above RB - Remediated-Below

S - Suspected R - Remediated

Report Generated: 11/11/2025 Page 1 of 2



Remedial Investigation and/or Feasibility Study

SHARP Assessment

Cleanup Site Details

ECOLOGY Cleanup S		etails	Clea	Cleanup Site ID: 4987		
SITE ACTIVITIES						
Activity		Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received		Completed		11/26/1990		
LUST - Notification		Completed		8/2/1993		
LUST - Report Received		Completed		8/2/1993		
Site Status Changed to NFA		Completed		2/8/1999		
Site Hazard Assessment		Canceled	1/1/2005	12/31/2006		
Reopen Site		Completed		7/24/2014		
Remedial Investigation and/or FS Work Plan		Completed	1/26/2015	6/12/2015		
Preparatory Action		Completed	2/4/2015	3/5/2015		
Order/Decree/Amendment		Canceled	3/5/2015	6/15/2015		
Order/Decree/Amendment		In Process	5/25/2018			
Remedial Investigation and/or FS Work Plan		Completed	4/1/2019	11/6/2019		
Remedial Investigation and/or FS Work Plan		Completed	5/1/2019	12/2/2019		

8/31/2019

3/21/2024

In Process

Completed