

# Cleanup Site Details

Cleanup Site ID: 4988

Cleanup Site ID: 4988      Facility/Site ID: 1127      UST ID: 3488      [Site Page](#)      [Site Documents](#)      [View Map](#)

Cleanup Site Name: Hungry Whale Grocery      [Glossary](#)

Alternate Names: Hungry Whale Grocery, HUNGRY WHALE MINI MART

## LOCATION

Address: 1680 NORTH MONTESANO ST      City: WESTPORT      Zip Code: 98595      County: Grays Harbor  
Latitude: 46.90216      Longitude: -124.10825      WRIA: 22      Legislative District: 19      Congressional District: 6      TRS: 16N 12W 1

## DETAIL

Status: Cleanup Started      NFA Received? No      Is PSI site? No  
Statute: MTCA      NFA Date: N/A      Current VCP? No      Past VCP? No  
Site Rank: 2 - Moderate-High Risk      NFA Reason: N/A      Brownfield? No  
Site Manager: Praisewater, Thomas      Responsible Unit: Southwest      Active Institutional Control? No

## CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
HUNGRY WHALE MINI MART	Upland	Cleanup Started	SW	Praisewater, Thomas	Ecology-supervised or conducted

## ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

## AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C	C				
Petroleum Products-Unspecified		C				
Petroleum-Other	C					

### Key:

B - Below Cleanup Level      C - Confirmed Above Cleanup Level      RA - Remediated-Above  
S - Suspected      R - Remediated      RB - Remediated-Below

## SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		11/25/1988
LUST - Notification	Completed		10/1/1990
Remedial Investigation and/or Feasibility Study	Completed	10/1/1991	4/1/1992
LUST - Report Received	Completed		3/10/1992
Cleanup Action - Engineering Design	Completed	10/1/1992	4/1/1993
Site Hazard Assessment/Federal Site Inspection	Completed	7/1/1993	7/20/1993
Hazardous Sites Listing/NPL	Completed		9/7/1993

# Cleanup Site Details

Cleanup Site ID: 4988

<b>SITE ACTIVITIES</b>			
<b>Activity</b>	<b>Status</b>	<b>Start Date</b>	<b>End Date/ Completion Date</b>
Cleanup Action - Engineering Design	Completed	6/1/1994	7/1/1996
Cleanup Action Plan	Completed	6/1/1994	4/1/1995
Order/Decree/Amendment	In Process	3/29/1995	
O & M	Completed	3/3/1996	10/1/1999
Cleanup - Construction	Completed	7/1/1997	10/1/1997
LUST - Report Received	Completed		12/4/2001
Order/Decree/Amendment	In Process	9/21/2006	
Remedial Investigation and/or Feasibility Study	Completed	5/1/2007	4/22/2020
Interim Action	Completed	9/1/2009	9/1/2010
Remedial Investigation and/or Feasibility Study	Completed	1/1/2011	4/25/2012
Initial Investigation / Federal Preliminary Assessment	Completed		6/1/2012
Initial Investigation / Federal Preliminary Assessment	Completed		8/6/2012
Order/Decree/Amendment	In Process	2/24/2016	
Cleanup Action Plan	Completed	4/22/2020	9/29/2021
Cleanup - Construction	Completed	7/1/2022	1/3/2024