

Cleanup Site Details

Cleanup Site ID: 499

Cleanup Site ID: 499 Facility/Site ID: 7646431 UST ID: 620227 [Site Page](#) [Site Documents](#) [View Map](#)

Cleanup Site Name: Duvall Market [Glossary](#)

Alternate Names: Duvall Market

LOCATION

Address: 15802 MAIN ST City: DUVALL Zip Code: 98019 County: King
Latitude: 47.74290 Longitude: -121.98557 WRIA: 7 Legislative District: 45 Congressional District: 1 TRS: 26N 6E 13

DETAIL

Status: No Further Action NFA Received? Yes Is PSI site? No
Statute: MTCA NFA Date: 9/26/2016 Current VCP? No Past VCP? Yes
Site Rank: N/A NFA Reason: Voluntary Cleanup Program Review Brownfield? No
Site Manager: Cardona, Tamara Responsible Unit: Northwest Active Institutional Control? No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Duvall Market	Upland	No Further Action Required	NW	Cardona, Tamara	Standard Voluntary Cleanup

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

MEDIA

Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Petroleum-Gasoline	RB					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/Completion Date
LUST - Notification	Completed		9/24/2002
LUST - Report Received	Completed		9/24/2002
VCP Opinion on Cleanup Action	Completed	9/24/2002	
VCP Status Request	Completed	3/31/2006	6/16/2006
LUST - Report Received	Completed		4/30/2015
VCP Opinion on Remedial Investigation	Completed	5/22/2015	6/9/2015
LUST - Report Received	Completed		7/30/2015
VCP Opinion on Site Cleanup	Completed	7/30/2015	9/23/2015
LUST - Report Received	Completed		10/13/2015

Cleanup Site Details

Cleanup Site ID: 499

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation Work Plan	Completed	10/13/2015	12/13/2015
LUST - Report Received	Completed		4/11/2016
LUST - Report Received	Completed		4/12/2016
VCP Opinion on Remedial Investigation	Completed	4/12/2016	5/26/2016
LUST - Report Received	Completed		8/9/2016
VCP Opinion on Remedial Investigation	Completed	8/9/2016	9/26/2016
Site Status Changed to NFA	Completed		9/26/2016
Petroleum Contaminated Soil Model Remedies	Completed		9/26/2016