

Cleanup Site Details

Cleanup Site ID: 499

Cleanup Site ID: 499	Facility/Site ID: 7646431	UST ID: 620227	Site Page	Site Documents	View Map	
Cleanup Site Name: Duvall Market					Glossary	
Alternate Names: Duvall Market						
LOCATION						
Address: 15802 MAIN ST		City: DUVALL	Zip Code: 98019	County: King		
Latitude: 47.74290	Longitude: -121.98557	WRIA: 7	Legislative District: 45	Congressional District: 1	TRS: 26N 6E 13	
DETAIL						
Status: No Further Action	NFA Received? Yes	Is PSI site? No				
Statute: MTCA	NFA Date: 9/26/2016	Current VCP? No	Past VCP? Yes			
Site Rank: N/A	NFA Reason: Voluntary Cleanup Program Review	Brownfield? No				
Site Manager: Cardona, Tamara	Responsible Unit: Northwest	Active Institutional Control? No				
CLEANUP UNITS						
Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process	
Duvall Market	Upland	No Further Action Required	NW	Cardona, Tamara	Standard Voluntary Cleanup	
ACTIVE INSTITUTIONAL CONTROLS						
Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
There are no current Institutional Controls in effect for this site.						
AFFECTED MEDIA & CONTAMINANTS						
MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Benzene	RB					
Petroleum-Gasoline	RB					
Key: B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above S - Suspected R - Remediated RB - Remediated-Below						
SITE ACTIVITIES						
Activity	Status	Start Date	End Date/ Completion Date			
LUST - Notification	Completed		9/24/2002			
LUST - Report Received	Completed		9/24/2002			
VCP Opinion on Cleanup Action	Completed	9/24/2002	1/1/1900			
VCP Status Request	Completed	3/31/2006	6/16/2006			
LUST - Report Received	Completed		4/30/2015			
VCP Opinion on Remedial Investigation	Completed	5/22/2015	6/9/2015			
LUST - Report Received	Completed		7/30/2015			
VCP Opinion on Site Cleanup	Completed	7/30/2015	9/23/2015			
LUST - Report Received	Completed		10/13/2015			
Toxics Cleanup Program		Report Generated: 8/19/2025		Page 1 of 2		

Cleanup Site Details

Cleanup Site ID: 499

SITE ACTIVITIES			
Activity	Status	Start Date	End Date/ Completion Date
VCP Opinion on Remedial Investigation Work Plan	Completed	10/13/2015	12/13/2015
LUST - Report Received	Completed		4/11/2016
LUST - Report Received	Completed		4/12/2016
VCP Opinion on Remedial Investigation	Completed	4/12/2016	5/26/2016
LUST - Report Received	Completed		8/9/2016
VCP Opinion on Remedial Investigation	Completed	8/9/2016	9/26/2016
Site Status Changed to NFA	Completed		9/26/2016
Petroleum Contaminated Soil Model Remedies	Completed		9/26/2016