

Cleanup Site Details

Cleanup Site ID: 50

Cleanup Site ID: 50 **Facility/Site ID:** 801 **UST ID:** N/A [Site Page](#) [Site Documents](#) [View Map](#)
Cleanup Site Name: UPRR Tekoa Line Segment 2 [Glossary](#)
Alternate Names: UPRR TEKOA LINE SEGMENT 2

LOCATION

Address: RR TRACK MI 118.40 **City:** TEKOA **Zip Code:** 99033 **County:** Whitman
Latitude: 47.23545 **Longitude:** -117.11907 **WRIA:** 56 **Legislative District:** 9 **Congressional District:** 5 **TRS:** 20N 45E 15

DETAIL

Status: Awaiting Cleanup **NFA Received?** No **Is PSI site?** No
Statute: MTCA **NFA Date:** N/A **Current VCP?** No **Past VCP?** No
Site Rank: 4 - Low-Moderate Risk **NFA Reason:** N/A **Brownfield?** No
Site Manager: Eastern Region **Responsible Unit:** Eastern **Active Institutional Control?** No

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
UPRR TEKOA LINE SEGMENT 2	Upland	Awaiting Cleanup	EA	Eastern Region	No Process

ACTIVE INSTITUTIONAL CONTROLS

Instrument Type	Restriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	-------------------	---------------------------	------	------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

Contaminant	MEDIA					
	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock
Metals Priority Pollutants	C					

Key:
B - Below Cleanup Level C - Confirmed Above Cleanup Level RA - Remediated-Above
S - Suspected R - Remediated RB - Remediated-Below

SITE ACTIVITIES

Activity	Status	Start Date	End Date/ Completion Date
Site Discovery/Release Report Received	Completed		2/28/1994
Initial Investigation / Federal Preliminary Assessment	Completed		4/14/1994
Early Notice Letter(s)	Completed		5/31/1994
Site Hazard Assessment/Federal Site Inspection	Completed	2/24/1999	7/27/1999
Hazardous Sites Listing/NPL	Completed		8/31/1999