

Cleanup Site ID: 5051

Cleanup Site Details

Facility/Site ID: 2030 UST ID: 97428 Site Page Site Documents View Map

Cleanup Site Name: Shell Oil Harbor Island Terminal

Alternate Names: EQUILON, EQUILON ENTERPRISES, EQUILON ENTERPRISES LLC, EQUILON ENTERPRISES LUBRICANTS PLANT, EQUILON SEATTLE DISTIBUTION TERMINAL, EQUILON SEATTLE DISTRIBUTION TERMINAL, Shell Oil Harbor Island Terminal, SHELL OIL

PRODUCT SEATTLE TERMINAL, SHELL OIL PRODUCTS US 13TH AVE SW, TEXACO MARKETING & REFINING HARBOR ISLAND

LOCATION

Address: 2555 13TH AVE SW City: SEATTLE Zip Code: 98134 County: King

Latitude: 47.58243 Longitude: -122.35206 WRIA: 9 Legislative District: 34 Congressional District: 7 TRS: 24N 4E 7

DETAIL

Status: Construction Complete-

Performance Monitoring

NFA Received?

No

Is PSI site?

Yes

No

No

D--41/000

Statute: MTCA

NFA Date:

N/A

Current VCP?

Past VCP? No

Cleanup Site ID: 5051

Site Rank: N/A

NFA Reason:

N/A

Brownfield?

No

Site Manager: Atkins, Vance

Responsible Unit: Northwest

Active Institutional Control?

CLEANUP UNITS

Cleanup Unit Name	Unit Type	Unit Status	Resp Unit	Unit Manager	Current Process
Shell Oil Products Harbor Island Terminal	Upland	Construction Complete- Performance Monitoring	NW	Atkins, Vance	Ecology-supervised or conducted

ACTIVE INSTITUTIONAL CONTROLS

Instrument Lyne	estriction Media	Restrictions/Requirements	Date	Recording Number	Recording County	Tax Parcel
-----------------	---------------------	---------------------------	------	---------------------	------------------	------------

There are no current Institutional Controls in effect for this site.

AFFECTED MEDIA & CONTAMINANTS

	MEDIA						
Contaminant	Soil	Groundwater	Surface Water	Sediment	Air	Bedrock	
Benzene	С	С					
Halogenated Organics	S	S	S				
Lead	С	С					
Metals - Other	S	S	S				
Metals Priority Pollutants	S		S				
Pesticides-Unspecified	S	S	S				
Petroleum-Diesel	С	С	RB				
Petroleum-Gasoline	С	С	RB				
Petroleum-Other	С	С	RB				
Polychlorinated biPhenyls (PCB)	S	S	S				
Polycyclic Aromatic Hydrocarbons	С	С	RB				

Key

B - Below Cleanup Level

S - Suspected

C - Confirmed Above Cleanup Level

R - Remediated

RA - Remediated-Above RB - Remediated-Below

Toxics Cleanup Program

Report Generated: 11/18/2025

Page 1 of 2



Cleanup Site Details

Cleanup Site	ID:	5051
--------------	-----	------

SITE ACTIVITIES					
Activity	Status	Start Date	End Date/ Completion Date		
Site Discovery/Release Report Received	Completed		3/1/1988		
Remedial Investigation and/or Feasibility Study	Completed	8/1/1988	7/1/1990		
LUST - Notification	Completed		8/19/1992		
National Priorities Listing	Completed		8/30/1992		
Remedial Investigation and/or Feasibility Study	Completed	3/1/1993	4/30/1997		
LUST - Report Received	Completed		3/21/1994		
LUST - Report Received	Completed		3/21/1994		
Cleanup Action Plan	Completed	12/12/1996	3/25/1999		
Order/Decree/Amendment	In Process	10/5/1998			
Cleanup Action - Engineering Design	Completed	4/9/1999	2/28/2002		
Cleanup - Construction	Completed	2/28/2002	6/1/2005		
Periodic Review	Completed	5/1/2005	7/31/2005		
Periodic Review	Completed		9/24/2010		
Initial Investigation / Federal Preliminary Assessment	Completed		4/21/2011		
Periodic Review	Completed		2/26/2015		
Cleanup - Performance Monitoring	In Process	4/1/2016			
Periodic Review	Completed	3/11/2020	9/16/2020		
LUST - Report Received	Completed		5/17/2021		
Non-LUST Ind Report Received	Completed		8/31/2021		
Non-LUST Ind Report Received	Completed		2/15/2022		
Non-LUST Ind Report Received	Completed		8/15/2022		
Non-LUST Ind Report Received	Completed		10/17/2022		
SHARP Assessment	Completed		4/15/2024		
Periodic Review	Planned	3/11/2025	1/1/1900		